Divi	ision of Envir Site Wastewa	onmental H ter Section SOIL/SI	ITE EVALUAT	FION	Sheet: Property ID: Lot #: File #: Code:				\$
Wate Evalu	er:	Applican 3 BEOX	Date LON Desi Prop	Evaluated: gn Flow (.1949): ろんて erty Recorded:	ell 🗌 Sprin	g 🗌 Oth	er		
P R O F I L F	.1940 Landscape	Horizon	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
E #	Position/ Slope %	Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
\	2-5%	0-48	GS	VFR NS INP					5.8
2		كالمر	G S	VFR ws)NP					5.8
					·····				
							-		
Descrin	tion	Initi		hir System					

Description Available Space (.1945)	Initial System	Repáir System	Other Factors (.1946): Site Classification (.1948): S Evaluated By: CX
System Type(s) Site LTAR	KON Q	CON	Others Present: β_{M}
	. 0		1

2×75 e 36-14"