

County of Harnett  
Building Inspections Department  
Planning Services

**Certificate of Compliance: x Occupancy: x**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: R-3

**Permit Numbers**

Name: Bill Clark Homes

Building: 11-50027466

Electrical: 11

Address: 441 Fifty Caliper Dr.

Insulation: 11

Plumbing: 11

Mechanical: 11

MFG Home: \_\_\_\_\_

Date: 1-10-12

Building Official: J. Michael Reavis

PREPARED 1/09/12, 14:17:37  
Harnett County

INSPECTION TICKET  
INSPECTOR: IVR

PAGE 16  
DATE 1/10/12

ADDRESS : 441 FIFTY CALIBER DR SUBDIV: PATTONS POINT  
CONTRACTOR : BILL CLARK HOMES LLC PHONE : (252) 355-5805  
OWNER : BILL CLARK HOMES PHONE : (910) 263-9026  
PARCEL : 03-9597- - -0039- -18-  
APPL NUMBER: 11-50027466 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : T/S: 09/01/2011 01:43 PM JBROCK ----  
27 TOWARDS 87 TURN LEFT ON TINGEN RD  
TURN LEFT INFO S-D ON STRIKE EAGLE DR  
TURN LEFT ON BUNKER BUSTER & LEFT ON  
FIFTY CALIBER DR LOT ON LEFT LOT 21

**STRUCTURE: 000 000 46X53 3BDR SLAB W/ GARAGE & PATIO**

FLOOD ZONE : FLOOD ZONE X  
# BEDROOMS : 3000000.00 PROPOSED USE : SFD  
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/13/11 10/13/11	MR AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002147882 T/S: 10/12/2011 12:05 PM DJOHNSON ----- FOOTING AND TSP INSPECTION EARLY MORNING, INSPECTION PLEASE T/S: 10/13/2011 12:07 PM MREARIC -----
A814 01	10/21/11 10/21/11	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002151777 441 FIFTY CALIBER DR LOT 21 BROADWAY 27505 T/S: 10/21/2011 12:02 PM TWARD -----
B103 01	10/21/11 10/21/11	MR AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002151769 T/S: 10/21/2011 12:37 PM MREARIC -----
P309 01	10/27/11 10/27/11	DT AP	R*PLUMB UNDER SLAB VRU #: 002154162
B111 01	10/31/11 10/31/11	MR AP	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002155232 WOULD LIKE AM INSPECTION T/S: 10/31/2011 01:10 PM MREARIC -----
R425 01	11/17/11 11/17/11	MR DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002162410 T/S: 11/16/2011 01:44 PM VBROWN ----- PAUL REQUEST AFTER LUNCH INSP. T/S: 11/17/2011 12:38 PM MREARIC ----- low water in riser, ok to insulate
I129 01	11/21/11 11/21/11	DT AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002163384
R425 02	11/21/11 11/21/11	DT AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002163392
H824 01	12/30/11 12/30/11	OT AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002177053 T/S: 01/03/2012 09:09 AM SZIMMER ----- T/S: 01/03/2012 09:12 AM SZIMMER -----
R429 01	1/04/12 1/04/12	MR CA	FOUR TRADE FINAL VRU #: 002177398 T/S: 01/04/2012 12:14 PM MREARIC -----
R429 02	1/06/12 1/06/12	MR DP	FOUR TRADE FINAL TIME: 17:00 VRU #: 002178325 T/S: 01/05/2012 12:17 PM VBROWN ----- 12 01:02 PM MREARIC ----- no attic insulation range outlet cover missing
R429 03	1/10/12	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002179380 T/S: 01/09/2012 12:04 PM VBROWN -----

1-10-12 AP-MR

COMMENTS AND NOTES