

COUNTY OF HARNETT  
Building Inspections Department  
Planning Services

**Certificate of Compliance:** \_\_\_\_\_ **Occupancy:**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Kenneth Moss

Address: 75 OAK Leaf Dr

\_\_\_\_\_

\_\_\_\_\_

Date: 10/27/15

Building Official: [Signature]

**Permit Numbers**

Building: \_\_\_\_\_

Electrical: \_\_\_\_\_

Insulation: \_\_\_\_\_

Plumbing: \_\_\_\_\_

Mechanical: \_\_\_\_\_

MFG Home: \_\_\_\_\_

5007 7959




ADDRESS : 75 OAK LEAF DR SUBDIV: SUMMERHILL  
 CONTRACTOR : MOSS KENNETH A PHONE : (910) 893-4875  
 OWNER : MANNING JERRY CHRISTOPHER PHONE :  
 PARCEL : 13-0539- - -0200- -10-  
 APPL NUMBER: 11-50027959 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : T/S: 11/29/2011 11:08 AM DJOHNSON --  
 SUMMERHILL LOT 3  
 TAKE MCDOUGALD RD FROM LILLINGTON ABOUT  
 6 MILES AND SUMMERHILL IS ON THE RIGHT.  
 RIGHT ON OAK LEAF DR.  
 PREMISE#:19987634

STRUCTURE: 000 000 53X39 3BDR CRAWL W/ GARAGE  
 FLOOD ZONE . . . . : FLOOD ZONE X  
 # BEDROOMS . . . . . : 3.00 PROPOSED USE . . . . . : SFD  
 SEPTIC - EXISTING? . . . . : NEW WATER SUPPLY . . . . . : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/20/15 7/20/15	MR AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002689842 would like am inspection T/S: 07/20/2015 03:55 PM MREARIC -----
B103 01	7/27/15 7/27/15	TSG AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 002694178 T/S: 07/29/2015 08:36 AM SGUY -----
A814 01	8/03/15 8/03/15	SB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002697431 75 OAK LEAF DR LILLINGTON 27546 T/S: 08/03/2015 10:22 AM SBENNETT -----
B105 01	8/03/15 8/03/15	TSG AP	R*OPEN FLOOR TIME: 17:00 VRU #: 002697449
R425 01	8/24/15 8/24/15	TSG DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002706885 1- GAS PRESSURE DOWN 2- DRYER VENT NOT COMPLETE. OK TO SIDE AND INSULATE
I129 01	8/27/15 8/27/15	TSG AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002709137
R425 02	8/27/15 8/27/15	TSG AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002709145
H824 01	9/02/15 9/02/15	OT AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002713600 T/S: 09/03/2015 11:55 AM SSTEWARD ----- T/S: 09/03/2015 11:56 AM SSTEWARD -----
E209 01	10/15/15 10/15/15	MR AP	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002730166 T/S: 10/15/2015 12:23 PM MREARIC -----
R429 01	10/26/15 10/26/15	TSG DA	FOUR TRADE FINAL TIME: 17:00 VRU #: 002734390 T/S: 10/23/2015 09:54 AM LBENNETT ----- 1-attic pull down required to be insulated to r-10 and weather stripping installed. N1102.2.3 2-garage door missing wind load cert sticker.
R429 02	10/26/15	TA AP	FOUR TRADE FINAL TIME: 17:00 VRU #: 002735181 T/S: 10/26/2015 01:49 PM LBENNETT -----



----- COMMENTS AND NOTES -----