		SOIL/S -SITE WA	SITE EVALUA ASTEWATER	TION SYSTEM		Property ID: Lot #: File #: Code:			
Addr Propo Locat Water Evalu	Owner: Applicant: Address: Date Evaluated: Proposed Facility: 3 & & & Design Flow (.1949): 3 & & & & & & & & & & & & & & & & & &								
P R O F I L E #	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	PROFILE FACTOR .1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
)	5-7%	0-45	G 5	VF.R.NSINP					S.X
2		0-48	Gs	VFR ~= /NP					s.
				·					ک، آ
_									
									<u> </u>
riptio	n pace (.1945)	Initia Syste	l Repai	r System Othe Site Cla	er Factors (.1946): ssification (.1948): <			<u>L</u>	

871