

County of Harnett  
Building Inspections Department  
Planning Services

**Certificate of Compliance: \_\_\_\_\_ Occupancy: ✓**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFO

**Permit Numbers**

Name: Hugh Stokes Builders  
LLC

Building: \_\_\_\_\_

Electrical: \_\_\_\_\_

Address: 112 Saw Grass Ct

Insulation: \_\_\_\_\_

Plumbing: \_\_\_\_\_

Mechanical: \_\_\_\_\_

MFG Home: \_\_\_\_\_

Date: 6-11-12

Building Official: \_\_\_\_\_

James Z Hall

43282005-01

ADDRESS : 112 SAW GRASS CT SUBDIV: WALNUT GROVE 37LOTS  
 CONTRACTOR : HUGH SURLS BUILDERS LLC PHONE : (919) 422-7065  
 OWNER : EVEN PAR DEVELOPMENT LLC PHONE :  
 PARCEL : 01-0525- - -0062- -33-  
 APPL NUMBER: 12-50028234 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 01/24/2012 10:14 AM JBROCK ----  
 210 S 10 MILES LEFT ON LASATER RD  
 WALNUT GROVE .5 MILES ON LEFT LOT 24

**STRUCTURE: 000 000 48X51 3BDR CRAWL W/ GARAGE**

FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3000000.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/09/12	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002190845
	2/09/12	AP	T-pole passed
B103 01	2/20/12	JH	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002194348
	2/20/12	AP	T/S: 02/17/2012 08:06 AM VBROWN
B105 01	3/15/12	MR	R*OPEN FLOOR VRU #: 002203494
	3/15/12	AP	T/S 03/15/2012 11:45 AM MREARIC
A814 01	4/09/12	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002212975
	4/05/12	AP	112 saw grass ct lot 24 bunlevel 28323 T/S: 04/05/2012 05:16 PM TWARD
R427 01	4/09/12	JH	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 002212967
	4/09/12	DA	1)add joist in garage on right side in back plans show a triple.2)missing stud to right of window in half bath over 16".3)missing roof boots on house.4)Pan drain for washer upstairs needs to go to the outside of the foundation wall.
I129 01	4/13/12	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002214716
	4/13/12	AP	T/S: 04/11/2012 02:45 PM DJOHNSON
R427 02	4/13/12	JH	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 002214708
	4/13/12	AP	T/S: 04/11/2012 02:45 PM DJOHNSON
H824 01	5/22/12	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002230753
	5/22/12	AP	T/S: 05/23/2012 09:20 AM SZIMMER
			T/S: 05/23/2012 09:21 AM SZIMMER
R431 01	6/11/12	TI	FOUR TRADE FINAL >2500 VRU #: 002237653

*6-11-12 [Signature]*

COMMENTS AND NOTES