Department of Environment, Health and Natural Resources
Division of Environmental Health
On-Site Wastewater Section

Sheet:
Property ID:
Lot #:
File #:
Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant:
Address:
Proposed Facility:
Location of Site:
Water Supply: ☑ Public ☐ Individual ☐ Well ☐ Spring ☐ Other
Evaluation Method: ☑ Auger Boring ☐ Pit ☐ Cut
Type of Wastewater: ☑ Sewage ☐ Industrial Process ☐ Mixed

Date Evaluated: 2/28/2012
Design Flow (.1949):
Property Recorded:
Property Size:

| PROFILE # | .1940 Landscape Position/ Slope % | Horizon Depth (In.) | SOIL MORPHOLOGY .1941 | | OTHER PROFILE FACTORS | | | | Profile Class & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| | | | .1941 Structure/ Texture | .1941 Consistence Mineralogy | .1942 Soil Wetness/ Color | .1943 Soil Depth (IN.) | .1956 Sapro Class | .1944 Restr Horiz | |
| | LS 4% | 0-18 | G/LS | VFr NS NP | | | | | |
| | | 18-31 | SCL/SCL | Fr SSSP | | | | | PS.6 |
| | | 31-48 | G/LS | VFr NS NP | | | | | |
| | | | | | | | | | |
| | | 0-16 | G/SL | VFr NS NP | | | | | |
| | | 16-40 | SCL/SCL | Fi SSSP | 10YR 7/1 @ 38" | | | | PS.4 |
| | | 40-48 | LS/G | VFr NS NP | | | | | |
| | | | | | | | | | |
| | | 0-16 | G/SL | VFr NS NP | | | | | |
| | | 16-48 | SCL/SCL | Fr SSSP | 10YR 7/1 @ 34 | | | | PS.5 |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| Description | Initial System | Repair System |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | Pump 25 ft. | Pump 25 ft. |
| Site LTAR | .5 | .4 |

Other Factors (.1946):
Site Classification (.1948): PS
Evaluated By: [illegible]
Others Present: