
ADDRESS : 520 JUNO DR SUBDIV: TINGEN POINTE PH 5 33LOTS
 CONTRACTOR : WYNN CONSTRUCTION, INC. PHONE : (919) 528-1347
 OWNER : THE HARNETT LAND GROUP II LLC PHONE :
 PARCEL : 03-9576-01- -0088- -27-
 APPL NUMBER: 12-50029197 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 06/19/2012 01:12 PM JBROCK ----
 HWY 27 W LEFT OMAHA DR LEFT ON JUNO LOT
 123

STRUCTURE: 000 000 50X55 3BDR MONO W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
A814 01	8/31/12	MR	ADDRESS CONFIRMATION VRU #: 002272359
	8/31/12	AP	T/S: 08/31/2012 02:17 PM MREARIC -----
P309 01	8/31/12	MR	R*PLUMB UNDER SLAB VRU #: 002272367
	8/31/12	AP	T/S: 08/31/2012 02:18 PM MREARIC -----
B114 01	9/04/12	TI	R*BLDG MONO SLAB/TEMP SVC POLE VRU #: 002273696

9-9-12 AP-MR

----- COMMENTS AND NOTES -----

*Res. check OK
T-Pole OK*

DAVID MILLER, PE
6300 Creedmoor Rd, STE 170#363
Raleigh, NC 27612
(919) 422-8932 (Office) ; DAVE@DMA-PA.COM

August 29, 2012

WYNN CONSTRUCTION
2550 CAPITAL DRIVE
SUITE 105
CREEDMOOR, NC 27522

E mailed to: jason@wynnconstruct.com ; keiths@davidsonandjones.com

RE: Engineering -- Field Observation
Lot 123 Tingen Pointe Subdivision
Lillington, Harnett County, NC
Job No.: 12DDM-0829B

To whom it may concern/ Inspections Dept.:

The undersigned arrived on-site to observe and test the in-place fill conditions for the above referenced site. Based on the testing (Per ASTM Special publication 399) the fill materials (Tan silty sands (Unified Soil Classification System – SM)) were adequately compacted (95% Standard Proctor) and adequate to support the planned structure. Based on the observations and testing the bearing soils for the footings will provide adequate support.

Sincerely,

David Miller, PE

DEM/12DDM-0829B

