

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:** ✓

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Name: Bonah Homes Inc

Address: 2737 Will Lucas Rd

Date: 11-13-12

Building Official: _____

James Hall

Permit Numbers
Building: _____
Electrical: _____
Insulation: _____
Plumbing: _____
Mechanical: _____
MFG Home: _____

10-500 89300

ADDRESS : 2733 WILL LUCAS RD SUBDIV:
 CONTRACTOR : BANAH HOMES INC PHONE : (919) 427-7524
 OWNER : BYRD CRAIG #3 PHONE : (910) 813-0194
 PARCEL : 01-0544- - -0011- -03-
 APPL NUMBER: 12-50029300 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 07/06/2012 08:17 AM DJOHNSON --
 TOSHIKO HERRING #3
 401 S TO BUNNLEVEL THEN RIGHT ON
 MCNEILL HOBBS RD LEFT ON WIRE RD RIGHT
 ON WIRE LUCAS RD LOT IS ON LEFT NEAR
 OTHER END OF RD. JUST PAST 2703

STRUCTURE: 000 000 52X36 2 BR ATT GARAGE SLAB

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 2.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	8/23/12	JH	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002269405
	8/23/12	AP	
A814 01	8/30/12	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002272292
	8/31/12	AP	2733 WILL LUCAS RD LOT 3 LINDEN 28356 T/S: 08/31/2012 03:49 PM TWARD
B103 01	8/31/12	FS	R*BLDG FOUND & TEMP SVC POLE VRU #: 002273043
	8/31/12	AP	T/S: 08/31/2012 03:02 PM FSPIVEY
P309 01	9/07/12	JH	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002275501
	9/07/12	AP	
B111 01	9/12/12	JH	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002277473
	9/12/12	AP	
R425 01	10/04/12	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002286094
	10/04/12	DA	1)Fire caulk @ top plate on back wall in garage.2)Missing anchor bolts on each side of door from garage to house.3)Fire caulk wire @ top plate to rifgt of kitchen window, you cant use insulation.4)Toilet flang needs to be installed per code.5)Missing nail guard on water line @ bottom plate in pantry.6)Furr top plate in coat closet @ front door.7)Fire caulk top plate @ dryer duct, not insulation.8)Need receptacle on front of house accessible from grade.
I129 01	10/08/12	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002288082
	10/08/12	DA	Code requires R15 in zone 4 in walls
R425 02	10/08/12	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002288108
	10/08/12	AP	
I129 02	10/09/12	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002288579
	10/09/12	AP	
H824 01	10/17/12	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002292738
	10/17/12	AP	T/S: 10/18/2012 09:08 AM SSTEWARD T/S: 10/18/2012 09:08 AM SSTEWARD
R429 01	11/13/12	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002300416

11-13-12 APJH

COMMENTS AND NOTES