

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: X **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: R-3

Name: H+H Constructors

Address: 204 Executive Dr.

Permit Numbers

Building: 12-50029568

Electrical:

Insulation:

Plumbing:

Mechanical:

MFG Home:

Date: 9-11-13

Building Official: T. Michael Ream

ADDRESS : 204 EXECUTIVE DR SUBDIV: OAKMONT PHASE 1 SECT1
 CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 OWNER : H & H CONSTRUCTION INC #26 PHONE :
 PARCEL : 03-0507- - -0046- -26-
 APPL NUMBER: 12-50029568 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 08/16/2012 03:49 PM DJOHNSON --
 27 W TO DOCS RD ON LEFT GO ABOUT 1.5
 MILES AND OAKMONT ON LEFT
 OAKMONT PHS 1 LOT 26

STRUCTURE: 000 000 55X51 5BDR ATT GARAGE PATIO SLAB

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 5.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/19/12	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002280337
	9/19/12	AP	T/S: 09/19/2012 01:26 PM MREARIC -----
A814 01	9/24/12	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002282143
	9/28/12	AP	204 EXECUTIVE DR LOT 26 LILLINGTON 27546--- T/S: 09/28/2012 08:42 AM TWARD -----
B103 01	9/24/12	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002282127
	9/24/12	AP	T/S: 09/24/2012 01:43 PM MREARIC -----
B105 01	9/27/12	MR	R*OPEN FLOOR TIME: 17:00 VRU #: 002284008
	9/27/12	CA	T/S: 09/27/2012 01:17 PM MREARIC ----- not ready and pier is in wrong spot
B105 02	9/28/12	MR	R*OPEN FLOOR TIME: 17:00 VRU #: 002284594
	9/28/12	AP	apS: 09/28/2012 12:37 PM MREARIC -----
R425 01	10/17/12	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002291995
	10/17/12	DA	T/S: 10/17/2012 10:34 AM MREARIC ----- sheath wing walls , instrall flashing on porches, switch torn off wall in garage, ok to insulate but not siding
I129 01	10/19/12	MR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002293165
	10/19/12	AP	T/S: 10/19/2012 01:19 PM MREARIC -----
R425 02	10/19/12	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002293173
	10/19/12	AP	T/S: 10/19/2012 01:20 PM MREARIC -----
P307 01	10/31/12	MR	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 002297638
	10/31/12	AP	T/S: 10/31/2012 12:23 PM MREARIC -----
H824 01	11/06/12	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002300473
	11/06/12	AP	T/S: 11/07/2012 10:50 AM SSTEWARD ----- T/S: 11/07/2012 10:50 AM SSTEWARD -----
E209 01	12/13/12	MR	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002315968
	12/13/12	AP	T/S: 12/13/2012 01:30 PM MREARIC -----
R429 01	9/11/13	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002437622

11 *AP-MR*

COMMENTS AND NOTES

ADDRESS : 204 EXECUTIVE DR SUBDIV: OAKMONT PHASE 1 SECT1
 CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 OWNER : H & H CONSTRUCTION INC #26 PHONE :
 PARCEL : 03-0507- - -0046- -26-
 APPL NUMBER: 12-50029568 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 08/16/2012 03:49 PM DJOHNSON --
 27 W TO DOCS RD ON LEFT GO ABOUT 1.5
 MILES AND OAKMONT ON LEFT
 OAKMONT PHS 1 LOT 26

STRUCTURE: 000 000 55X51 5BDR ATT GARAGE PATIO SLAB

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 5.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/19/12	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002280337
	9/19/12	AP	T/S: 09/19/2012 01:26 PM MREARIC
A814 01	9/24/12	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002282143
	9/28/12	AP	204 EXECUTIVE DR LOT 26 LILLINGTON 27546---
			T/S: 09/28/2012 08:42 AM TWARD
B103 01	9/24/12	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002282127
	9/24/12	AP	T/S: 09/24/2012 01:43 PM MREARIC
B105 01	9/27/12	MR	R*OPEN FLOOR TIME: 17:00 VRU #: 002284008
	9/27/12	CA	T/S: 09/27/2012 01:17 PM MREARIC
			not ready and pier is in wrong spot
B105 02	9/28/12	MR	R*OPEN FLOOR TIME: 17:00 VRU #: 002284594
	9/28/12	AP	apS: 09/28/2012 12:37 PM MREARIC
R425 01	10/17/12	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002291995
	10/17/12	DA	T/S: 10/17/2012 10:34 AM MREARIC
			sheath wing walls , instrall flashing on porches, switch torn off wall in garage, ok to insulate but not siding
I129 01	10/19/12	MR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002293165
	10/19/12	AP	T/S: 10/19/2012 01:19 PM MREARIC
R425 02	10/19/12	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002293173
	10/19/12	AP	T/S: 10/19/2012 01:20 PM MREARIC
P307 01	10/31/12	MR	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 002297638
	10/31/12	AP	T/S: 10/31/2012 12:23 PM MREARIC
H824 01	11/06/12	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002300473
	11/06/12	AP	T/S: 11/07/2012 10:50 AM SSTEWARD
			T/S: 11/07/2012 10:50 AM SSTEWARD
E209 01	12/13/12	TI	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002315968

12.13.12 AP.MR

COMMENTS AND NOTES