

ADDRESS : 216 EXECUTIVE DR
 CONTRACTOR : H & H CONSTRUCTORS INC
 OWNER : H & H CONSTRUCTION #27
 PARCEL : 03-0507- - -0046- -27-
 APPL NUMBER: 12-50029569 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 08/16/2012 03:54 PM DJOHNSON --
 OAKMONT PHS 1 #27 27W TO DOCS RD TURN
 LEFT GO 1.5 MILES AND TURN LEFT ON
 OAKMONT.

SUBDIV: OAKMONT PHASE 1 SECT1
 PHONE : (910) 486-4864
 PHONE : (910) 486-4864

STRUCTURE: 000 000 40X52 4 BR ATT GARAGE PATIO PORCH #27CRW

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00
 SEPTIC - EXISTING? : NEW TANK
 PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/20/12	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002280584
	9/20/12	AP	T/S: 09/20/2012 01:00 PM MREARIC -----
A814 01	9/24/12	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002282168
	9/28/12	AP	216 EXECUTIVE DR LOT 27 LILLINGTON 27546----- T/S: 09/28/2012 08:43 AM TWARD -----
B103 01	9/24/12	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002282150
	9/24/12	AP	T/S: 09/24/2012 01:43 PM MREARIC -----
B105 01	9/28/12	MR	R*OPEN FLOOR TIME: 17:00 VRU #: 002284560
	9/28/12	AP	T/S: 09/28/2012 12:37 PM MREARIC -----
R425 01	10/17/12	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002292001
	10/17/12	DA	T/S: 10/17/2012 10:35 AM MREARIC ----- sheath wing walls, install flashing on porches, crawlspace opening too small, ok to insulate but no siding yet.
I129 01	10/19/12	MR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002293140
	10/19/12	AP	T/S: 10/19/2012 01:20 PM MREARIC -----
R425 02	10/19/12	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002293157
	10/19/12	AP	T/S: 10/19/2012 01:20 PM MREARIC -----
P307 01	10/31/12	MR	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 002297620
	10/31/12	AP	T/S: 10/31/2012 12:23 PM MREARIC -----
H824 01	11/13/12	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002303402
	11/13/12	AP	T/S: 11/14/2012 11:35 AM SSTEWARD ----- T/S: 11/14/2012 11:35 AM SSTEWARD -----
E209 01	12/14/12	MR	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002316503
	12/14/12	DA	T/S: 12/14/2012 01:32 PM MREARIC ----- wiring not complete / house locked
E209 02	1/14/13	MR	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002326569
	1/14/13	DA	013 01:54 PM MREARIC ----- house locked
E209 03	1/16/13	MR	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002327393
	1/16/13	AP	T/S: 01/16/2013 12:02 PM MREARIC -----
R429 01	3/05/13	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002346500

3-5-13 DP-MR

COMMENTS AND NOTES

HARNETT COUNTY

Building Inspections Dept.

108 E. Front St.

Lillington, NC 27546

910-893-7525

DATE: 03/05/2013

PERMIT # 12-50029569

ADDRESS: 216 Executive

1. Window fall protection on dining room window
2. Cannot find an energy compliance certificate at the panel ,
attic or the kitchen cabinet

Mike Rearic cell# (910) 984- 4772