Department of Environment, Health and Natu Division of Environmental Health On-Site Wastewater Section

Applicant:

Owner:

Resources

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

System

Available Space (.1945) System Type(s)

Site LTAR

Locati Water Evalua	ess: sed Facility: on of Site: Supply: ation Method of Wastewate	l: Xauge	Des Prop Public	e Evaluated: ign Flow (.1949): September (.1949): S	Well Spring		aer		2
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1-14	F-7	13	SVITABL	£ LESSTIN	1022" MC	AY			
	SEE B	00F	LES ON	PROPOSA	L				
			<i>Y</i>						
	REPAR	x 2026	M 0-	42" 6	s variable	5.8	-		
						т.			
			· · · · · · · · · · · · · · · · · · ·						
								-	8
Descrip	tion	Ini	tial Re	pair System	Other Factors (.1946):				

Site Classification (.1948):

Others Present:

Evaluated By:05 /mE

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	<u>TEXTURES</u>	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

SIC-SILTY CLAY 0.4 - 0.1 IV

C-CLAY SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

