

ADDRESS : 70 BISON LN SUBDIV: OAKMONT PH1 SECT2 25LOTS
 CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 OWNER : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 PARCEL : 03-0507- - -0046- -38-
 APPL NUMBER: 12-50030140 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 11/21/2012 11:51 AM JBROCK ----
 TAKE HWY 27 TO DOCS RD TURN LEFT GO
 ABOUT 1.5 MILES TURN LEFT INTO S/D LOT
 33

STRUCTURE: 000 000 61X36 4BDR SALB W/ GARAGE & SLAB

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/05/13	MR	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002335057
	2/05/13	AP	T/S: 02/05/2013 12:43 PM MREARIC -----
A814 01	2/08/13	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002337053
	2/19/13	AP	70 bison ln lot 33 lillington 27546
			T/S: 02/19/2013 01:23 PM TWARD -----
B103 01	2/08/13	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002337046
	2/08/13	AP	T/S: 02/08/2013 01:05 PM MREARIC -----
B104 01	2/25/13	JB	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 002343747
	2/25/13	AP	T/S: 02/25/2013 04:09 PM JBROCK -----
E207 01	2/25/13	MR	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 002342848
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN -----
			T/S: 02/25/2013 12:51 PM MREARIC -----
P309 01	2/25/13	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002342830
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN -----
			T/S: 02/25/2013 12:51 PM MREARIC -----
B111 01	3/04/13	MR	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002346476
	3/04/13	AP	T/S: 03/04/2013 01:43 PM MREARIC -----
R425 01	3/20/13	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002354041
	3/20/13	DA	T/S: 03/20/2013 01:26 PM MREARIC -----
			1. bolts to be within 12" of ends in sill plates
			2. air barriers not complete in front room over garage
			3. seal floor in that room also
			4. stud needed in back 2nd fl. bedroom where over 24"
			5. no baffles
			6. no pressure or riser water
			7. raise toilet flange in mbr to floor elevation
			8. strap both ends of large LVL over living room for 2000#
			on each end
R425 02	3/25/13	FS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002356160
	3/25/13	AP	T/S: 03/25/2013 02:52 PM FSPIVEY -----
I129 01	3/28/13	BS	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002358083
	3/28/13	DP	T/S: 03/27/2013 11:23 AM VBROWN -----
			T/S: March 28, 2013 09:16 AM BSUTTON -----
			No insulation behind downstairs shower. DO NOT SHEETROCK
			SINGLE CAR GARAGE. Call to reschedule
I129 02	4/01/13	MR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002358893
	4/01/13	AP	T/S: 04/01/2013 01:21 PM MREARIC -----

ADDRESS : 70 BISON LN
CONTRACTOR : H & H CONSTRUCTORS INC
OWNER : H & H CONSTRUCTORS INC
PARCEL : 03-0507- - -0046- -38-
APPL NUMBER: 12-50030140 CP NEW RESIDENTIAL (SFD)

SUBDIV: OAKMONT PH1 SECT2 25LOTS
PHONE : (910) 486-4864
PHONE : (910) 486-4864

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
H824 01	4/15/13	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002368520
	4/15/13	AP	T/S: 04/17/2013 09:46 AM SSTEWARD -----
R125 01	4/19/13	MR	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002369759
	4/19/13	AP	STONE WIRE CHECK T/S: 04/19/2013 01:26 PM MREARIC -----
E209 01	4/24/13	MR	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002371813
	4/24/13	CA	T/S: 04/24/2013 12:06 PM MREARIC -----
E209 02	4/25/13	MR	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002372373
	4/25/13	AP	T/S: 04/25/2013 01:52 PM MREARIC -----
R429 01	4/30/13	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002374031

4-30-13 AP MR

----- COMMENTS AND NOTES -----

Harnett County

INSPECTOR: IVR

DATE

4/25/13

 ADDRESS : 70 BISON LN
 CONTRACTOR : H & H CONSTRUCTORS INC
 OWNER : H & H CONSTRUCTORS INC
 PARCEL : 03-0507- - -0046- -38-
 APPL NUMBER: 12-50030140 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 11/21/2012 11:51 AM JBROCK ----
 TAKE HWY 27 TO DOCS RD TURN LEFT GO
 ABOUT 1.5 MILES TURN LEFT INTO S/D LOT
 33

SUBDIV: OAKMONT PH1 SECT2 25LOTS
 PHONE : (910) 486-4864
 PHONE : (910) 486-4864

STRUCTURE: 000 000 61X36 4BDR SALB W/ GARAGE & SLAB

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4000000.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/05/13	MR	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002335057
	2/05/13	AP	T/S: 02/05/2013 12:43 PM MREARIC -----
A814 01	2/08/13	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002337053
	2/19/13	AP	70 bison ln lot 33 lillington 27546 ---- T/S: 02/19/2013 01:23 PM TWARD -----
B103 01	2/08/13	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002337046
	2/08/13	AP	T/S: 02/08/2013 01:05 PM MREARIC -----
B104 01	2/25/13	JB	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 002343747
	2/25/13	AP	T/S: 02/25/2013 04:09 PM JBROCK -----
E207 01	2/25/13	MR	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 002342848
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN ----- T/S: 02/25/2013 12:51 PM MREARIC -----
P309 01	2/25/13	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002342830
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN ----- T/S: 02/25/2013 12:51 PM MREARIC -----
B111 01	3/04/13	MR	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002346476
	3/04/13	AP	T/S: 03/04/2013 01:43 PM MREARIC -----
R425 01	3/20/13	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002354041
	3/20/13	DA	T/S: 03/20/2013 01:26 PM MREARIC ----- 1. bolts to be within 12" of ends in sill plates 2. air barriers not complete in front room over garage 3. seal floor in that room also 4. stud needed in back 2nd fl. bedroom where over 24" 5. no baffles 6. no pressure or riser water 7. raise toilet flange in mbr to floor elevation 8. strap both ends of large LVL over living room for 2000# on each end
R425 02	3/25/13	FS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002356160
	3/25/13	AP	T/S: 03/25/2013 02:52 PM FSPIVEY -----
I129 01	3/28/13	BS	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002358083
	3/28/13	DP	T/S: 03/27/2013 11:23 AM VBROWN ----- T/S: March 28, 2013 09:16 AM BSUTTON ----- No insulation behind downstairs shower. DO NOT SHEETROCK SINGLE CAR GARAGE. Call to reschedule
I129 02	4/01/13	MR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002358893
	4/01/13	AP	T/S: 04/01/2013 01:21 PM MREARIC -----

ADDRESS : 70 BISON LN
CONTRACTOR : H & H CONSTRUCTORS INC
OWNER : H & H CONSTRUCTORS INC
PARCEL : 03-0507- - -0046- -38-
APPL NUMBER: 12-50030140 CP NEW RESIDENTIAL (SFD)

SUBDIV: OAKMONT PH1 SECT2 25LOTS
PHONE : (910) 486-4864
PHONE : (910) 486-4864

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
H824 01	4/15/13	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002368520
	4/15/13	AP	T/S: 04/17/2013 09:46 AM SSTEWARD -----
R125 01	4/19/13	MR	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002369759
	4/19/13	AP	STONE WIRE CHECK T/S: 04/19/2013 01:26 PM MREARIC -----
E209 01	4/24/13	MR	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002371813
	4/24/13	CA	T/S: 04/24/2013 12:06 PM MREARIC -----
E209 02	4/25/13	TI	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002372373

4-25-13

~~DA-MR~~
~~AP-MR~~

COMMENTS AND NOTES

~~Not finished~~
Finished

ADDRESS : 70 BISON LN SUBDIV: OAKMONT PH1 SECT2 25LOTS
 CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 OWNER : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 PARCEL : 03-0507- - -0046- -38-
 APPL NUMBER: 12-50030140 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 11/21/2012 11:51 AM JBROCK ----
 TAKE HWY 27 TO DOCS RD TURN LEFT GO
 ABOUT 1.5 MILES TURN LEFT INTO S/D LOT
 33

STRUCTURE: 000 000 61X36 4BDR SALB W/ GARAGE & SLAB
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/05/13	MR	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002335057
	2/05/13	AP	T/S: 02/05/2013 12:43 PM MREARIC -----
A814 01	2/08/13	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002337053
	2/19/13	AP	70 bison ln lot 33 lillington 27546 ---- T/S: 02/19/2013 01:23 PM TWARD -----
B103 01	2/08/13	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002337046
	2/08/13	AP	T/S: 02/08/2013 01:05 PM MREARIC -----
B104 01	2/25/13	JB	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 002343747
	2/25/13	AP	T/S: 02/25/2013 04:09 PM JBROCK -----
E207 01	2/25/13	MR	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 002342848
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN ----- T/S: 02/25/2013 12:51 PM MREARIC -----
P309 01	2/25/13	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002342830
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN ----- T/S: 02/25/2013 12:51 PM MREARIC -----
B111 01	3/04/13	MR	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002346476
	3/04/13	AP	T/S: 03/04/2013 01:43 PM MREARIC -----
R425 01	3/20/13	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002354041
	3/20/13	DA	T/S: 03/20/2013 01:26 PM MREARIC ----- 1. bolts to be within 12" of ends in sill plates 2. air barriers not complete in front room over garage 3. seal floor in that room also 4. stud needed in back 2nd fl. bedroom where over 24" 5. no baffles 6. no pressure or riser water 7. raise toilet flange in mbr to floor elevation 8. strap both ends of large LVL over living room for 2000# on each end
R425 02	3/25/13	FS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002356160
	3/25/13	AP	T/S: 03/25/2013 02:52 PM FSPIVEY -----
I129 01	3/28/13	BS	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002358083
	3/28/13	DP	T/S: 03/27/2013 11:23 AM VBROWN ----- T/S: March 28, 2013 09:16 AM BSUTTON ----- No insulation behind downstairs shower. DO NOT SHEETROCK SINGLE CAR GARAGE. Call to reschedule
I129 02	4/01/13	MR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002358893
	4/01/13	AP	T/S: 04/01/2013 01:21 PM MREARIC -----

ADDRESS : 70 BISON LN SUBDIV: OAKMONT PH1 SECT2 25LOTS
CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
OWNER : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
PARCEL : 03-0507- - -0046- -38-
APPL NUMBER: 12-50030140 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
H824 01	4/15/13	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002368520
	4/15/13	AP	T/S: 04/17/2013 09:46 AM SSTEWARD -----
R125 01	4/19/13	MR	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002369759
	4/19/13	AP	STONE WIRE CHECK
			T/S: 04/19/2013 01:26 PM MREARIC -----
E209 01	4/24/13	TI	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002371813
	<u>4-24-13</u>	<u>CA-MR</u>	

----- COMMENTS AND NOTES -----

ADDRESS : 70 BISON LN SUBDIV: OAKMONT PH1 SECT2 25LOTS
 CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 OWNER : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 PARCEL : 03-0507- - -0046- -38-
 APPL NUMBER: 12-50030140 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : T/S: 11/21/2012 11:51 AM JBROCK ----
 TAKE HWY 27 TO DOCS RD TURN LEFT GO
 ABOUT 1.5 MILES TURN LEFT INTO S/D LOT
 33

STRUCTURE: 000 000 61X36 4BDR SALB W/ GARAGE & SLAB
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/05/13	MR	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002335057
	2/05/13	AP	T/S: 02/05/2013 12:43 PM MREARIC -----
A814 01	2/08/13	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002337053
	2/19/13	AP	70 bison ln lot 33 lillington 27546 ---- T/S: 02/19/2013 01:23 PM TWARD -----
B103 01	2/08/13	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002337046
	2/08/13	AP	T/S: 02/08/2013 01:05 PM MREARIC -----
B104 01	2/25/13	JB	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 002343747
	2/25/13	AP	T/S: 02/25/2013 04:09 PM JBROCK -----
E207 01	2/25/13	MR	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 002342848
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN ----- T/S: 02/25/2013 12:51 PM MREARIC -----
P309 01	2/25/13	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002342830
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN ----- T/S: 02/25/2013 12:51 PM MREARIC -----
B111 01	3/04/13	MR	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002346476
	3/04/13	AP	T/S: 03/04/2013 01:43 PM MREARIC -----
R425 01	3/20/13	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002354041
	3/20/13	DA	T/S: 03/20/2013 01:26 PM MREARIC ----- 1. bolts to be within 12" of ends in sill plates 2. air barriers not complete in front room over garage 3. seal floor in that room also 4. stud needed in back 2nd fl. bedroom where over 24" 5. no baffles 6. no pressure or riser water 7. raise toilet flange in mbr to floor elevation 8. strap both ends of large LVL over living room for 2000# on each end
R425 02	3/25/13	FS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002356160
	3/25/13	AP	T/S: 03/25/2013 02:52 PM FSPIVEY -----
I129 01	3/28/13	BS	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002358083
	3/28/13	DP	T/S: 03/27/2013 11:23 AM VBROWN ----- T/S: March 28, 2013 09:16 AM BSUTTON ----- No insulation behind downstairs shower. DO NOT SHEETROCK SINGLE CAR GARAGE. Call to reschedule
I129 02	4/01/13	MR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002358893

Harnett County

INSPECTOR: IVR

DATE 4/19/13

ADDRESS : 70 BISON LN
 CONTRACTOR : H & H CONSTRUCTORS INC
 OWNER : H & H CONSTRUCTORS INC
 PARCEL : 03-0507- - -0046- -38-
 APPL NUMBER: 12-50030140 CP NEW RESIDENTIAL (SFD)

SUBDIV: OAKMONT PH1 SECT2 25LOTS
 PHONE : (910) 486-4864
 PHONE : (910) 486-4864

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
H824 01	4/01/13	AP	T/S: 04/01/2013 01:21 PM MREARIC -----
	4/15/13	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002368520
	4/15/13	AP	T/S: 04/17/2013 09:46 AM SSTEWARD -----
R125 01	4/19/13	TI	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002369759
	<u>4-19-13</u>	<u>AP-MR</u>	STONE WIRE CHECK

----- COMMENTS AND NOTES -----

ADDRESS : 70 BISON LN SUBDIV: OAKMONT PH1 SECT2 25LOTS
 CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 OWNER : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 PARCEL : 03-0507- - -0046- -38-
 APPL NUMBER: 12-50030140 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 11/21/2012 11:51 AM JBROCK ----
 TAKE HWY 27 TO DOCS RD TURN LEFT GO
 ABOUT 1.5 MILES TURN LEFT INTO S/D LOT
 33

STRUCTURE: 000 000 61X36 4BDR SALB W/ GARAGE & SLAB

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/05/13	MR	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002335057
	2/05/13	AP	T/S: 02/05/2013 12:43 PM MREARIC -----
A814 01	2/08/13	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002337053
	2/19/13	AP	70 bison ln lot 33 lillington 27546 ---- T/S: 02/19/2013 01:23 PM TWARD -----
B103 01	2/08/13	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002337046
	2/08/13	AP	T/S: 02/08/2013 01:05 PM MREARIC -----
B104 01	2/25/13	JB	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 002343747
	2/25/13	AP	T/S: 02/25/2013 04:09 PM JBROCK -----
E207 01	2/25/13	MR	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 002342848
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN ----- T/S: 02/25/2013 12:51 PM MREARIC -----
P309 01	2/25/13	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002342830
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN ----- T/S: 02/25/2013 12:51 PM MREARIC -----
B111 01	3/04/13	MR	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002346476
	3/04/13	AP	T/S: 03/04/2013 01:43 PM MREARIC -----
R425 01	3/20/13	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002354041
	3/20/13	DA	T/S: 03/20/2013 01:26 PM MREARIC ----- 1. bolts to be within 12" of ends in sill plates 2. air barriers not complete in front room over garage 3. seal floor in that room also 4. stud needed in back 2nd fl. bedroom where over 24" 5. no baffles 6. no pressure or riser water 7. raise toilet flange in mbr to floor elevation 8. strap both ends of large LVL over living room for 2000# on each end
R425 02	3/25/13	FS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002356160
	3/25/13	AP	T/S: 03/25/2013 02:52 PM FSPIVEY -----
I129 01	3/28/13	BS	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002358083
	3/28/13	DP	T/S: 03/27/2013 11:23 AM VBROWN ----- T/S: March 28, 2013 09:16 AM BSUTTON ----- No insulation behind downstairs shower. DO NOT SHEETROCK SINGLE CAR GARAGE. Call to reschedule
I129 02	4/01/13	TI	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002358893

4-1-13 AP/IVR

ADDRESS : 70 BISON LN SUBDIV: OAKMONT PH1 SECT2 25LOTS
 CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 OWNER : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 PARCEL : 03-0507- - -0046- -38-
 APPL NUMBER: 12-50030140 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 11/21/2012 11:51 AM JBROCK ----
 TAKE HWY 27 TO DOCS RD TURN LEFT GO
 ABOUT 1.5 MILES TURN LEFT INTO S/D LOT
 33

STRUCTURE: 000 000 61X36 4BDR SALB W/ GARAGE & SLAB

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/05/13	MR	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002335057
	2/05/13	AP	T/S: 02/05/2013 12:43 PM MREARIC -----
A814 01	2/08/13	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002337053
	2/19/13	AP	70 bison ln lot 33 lillington 27546 ---- T/S: 02/19/2013 01:23 PM TWARD -----
B103 01	2/08/13	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002337046
	2/08/13	AP	T/S: 02/08/2013 01:05 PM MREARIC -----
B104 01	2/25/13	JB	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 002343747
	2/25/13	AP	T/S: 02/25/2013 04:09 PM JBROCK -----
E207 01	2/25/13	MR	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 002342848
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN ----- T/S: 02/25/2013 12:51 PM MREARIC -----
P309 01	2/25/13	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002342830
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN ----- T/S: 02/25/2013 12:51 PM MREARIC -----
B111 01	3/04/13	MR	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002346476
	3/04/13	AP	T/S: 03/04/2013 01:43 PM MREARIC -----
R425 01	3/20/13	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002354041
	3/20/13	DA	T/S: 03/20/2013 01:26 PM MREARIC ----- 1. bolts to be within 12" of ends in sill plates 2. air barriers not complete in front room over garage 3. seal floor in that room also 4. stud needed in back 2nd fl. bedroom where over 24" 5. no baffles 6. no pressure or riser water 7. raise toilet flange in mbr to floor elevation 8. strap both ends of large LVL over living room for 2000# on each end
R425 02	3/25/13	FS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002356160
	3/25/13	AP	T/S: 03/25/2013 02:52 PM FSPIVEY -----
I129 01	3/28/13	TI	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002358083
	<u>3-28-13</u>	<u>OPB</u>	T/S: 03/27/2013 11:23 AM VBROWN -----

COMMENTS AND NOTES

ADDRESS : 70 BISON LN
 CONTRACTOR : H & H CONSTRUCTORS INC
 OWNER : H & H CONSTRUCTORS INC
 PARCEL : 03-0507- - -0046- -38-
 APPL NUMBER: 12-50030140 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 11/21/2012 11:51 AM JBROCK ----
 TAKE HWY 27 TO DOCS RD TURN LEFT GO
 ABOUT 1.5 MILES TURN LEFT INTO S/D LOT
 33


SUBDIV: OAKMONT PH1 SECT2 25LOTS
 PHONE : (910) 486-4864
 PHONE : (910) 486-4864

STRUCTURE: 000 000 61X36 4BDR SALB W/ GARAGE & SLAB

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4000000.00
 SEPTIC - EXISTING? : NEW
 PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/05/13	MR	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002335057
	2/05/13	AP	T/S: 02/05/2013 12:43 PM MREARIC -----
A814 01	2/08/13	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002337053
	2/19/13	AP	70 bison ln lot 33 lillington 27546 ---- T/S: 02/19/2013 01:23 PM TWARD -----
B103 01	2/08/13	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002337046
	2/08/13	AP	T/S: 02/08/2013 01:05 PM MREARIC -----
B104 01	2/25/13	JB	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 002343747
	2/25/13	AP	T/S: 02/25/2013 04:09 PM JBROCK -----
E207 01	2/25/13	MR	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 002342848
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN ----- T/S: 02/25/2013 12:51 PM MREARIC -----
P309 01	2/25/13	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002342830
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN ----- T/S: 02/25/2013 12:51 PM MREARIC -----
B111 01	3/04/13	MR	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002346476
	3/04/13	AP	T/S: 03/04/2013 01:43 PM MREARIC -----
R425 01	3/20/13	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002354041
	3/20/13	DA	T/S: 03/20/2013 01:26 PM MREARIC ----- 1. bolts to be within 12" of ends in sill plates 2. air barriers not complete in front room over garage 3. seal floor in that room also 4. stud needed in back 2nd fl. bedroom where over 24" 5. no baffles 6. no pressure or riser water 7. raise toilet flange in mbr to floor elevation 8. strap both ends of large LVL over living room for 2000# on each end
R425 02	3/25/13	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002356160

3/25/13 AP


COMMENTS AND NOTES -----

Harratt County

INSPECTOR: IVR

DATE 3/20/13

ADDRESS : 70 BISON LN
 CONTRACTOR : H & H CONSTRUCTORS INC
 OWNER : H & H CONSTRUCTORS INC
 PARCEL : 03-0507- - -0046- -38-
 APPL NUMBER: 12-50030140 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 11/21/2012 11:51 AM JBROCK ----
 TAKE HWY 27 TO DOCS RD TURN LEFT GO
 ABOUT 1.5 MILES TURN LEFT INTO S/D LOT
 33

SUBDIV: OAKMONT PH1 SECT2 25LOTS
 PHONE : (910) 486-4864
 PHONE : (910) 486-4864

STRUCTURE: 000 000 61X36 4BDR SALB W/ GARAGE & SLAB

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4000000.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/05/13	MR	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002335057
	2/05/13	AP	T/S: 02/05/2013 12:43 PM MREARIC -----
A814 01	2/08/13	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002337053
	2/19/13	AP	70 bison ln lot 33 lillington 27546 ---- T/S: 02/19/2013 01:23 PM TWARD -----
B103 01	2/08/13	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002337046
	2/08/13	AP	T/S: 02/08/2013 01:05 PM MREARIC -----
B104 01	2/25/13	JB	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 002343747
	2/25/13	AP	T/S: 02/25/2013 04:09 PM JBROCK -----
E207 01	2/25/13	MR	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 002342848
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN ----- T/S: 02/25/2013 12:51 PM MREARIC -----
P309 01	2/25/13	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002342830
	2/25/13	AP	T/S: 02/22/2013 03:13 PM VBROWN ----- T/S: 02/25/2013 12:51 PM MREARIC -----
B111 01	3/04/13	MR	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002346476
	3/04/13	AP	T/S: 03/04/2013 01:43 PM MREARIC -----
R425 01	3/20/13	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002354041

3-20-13 DAMIR

COMMENTS AND NOTES

HARNETT COUNTY

Building Inspections Dept.

108 E. Front St.

Lillington, NC 27546

910-893-7525

DATE: 03/20/2013

PERMIT # 12-50030140

ADDRESS: 70 bison lane

1. Bolts in sill within 12" of ends needed
2. Front closet upstairs needs the air barriers on all wall sections and seal the floor cracks at perimeters, and all holes in floor membrane everywhere
3. Stud needed where over 24" in 2nd fl. Back bedroom wall
4. No baffles installed
5. No water pressure or water in riser
6. Bring flange in master bedroom to floor height and secure
7. Strap both ends of the large lvl across living room at both end for a min. of 2000# at each end

Mike Rearic cell# (910) 984- 4772

ADDRESS : 25 BLAKELY CT SUBDIV: OAKMONT PH1 SECT2 25LOTS
 CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 OWNER : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 PARCEL : 03-0507- - -0046- -38-
 APPL NUMBER: 12-50030140 CP-NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 11/21/2012 11:51 AM JBROCK ----
 TAKE HWY 27 TO DOCS RD TURN LEFT GO
 ABOUT 1.5 MILES TURN LEFT INTO S/D LOT
 33

STRUCTURE: 000 000 61X36 4BDR SALB W/ GARAGE & SLAB
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS	TIME:	VRU #:
B101 01	2/05/13 <u>2-5-13</u>	TI <u>AP-MR</u>	R*BLDG FOOTING / TEMP SVC POLE	17:00	002335057

----- COMMENTS AND NOTES -----

ADDRESS : 25 BLAKELY CT
CONTRACTOR : H & H CONSTRUCTORS INC
OWNER : H & H CONSTRUCTORS INC
PARCEL : 03-0507- - -0046- -38-
APPL NUMBER: 12-50030140 CP NEW RESIDENTIAL (SFD)

SUBDIV: OAKMONT PH1 SECT2 25LOTS
PHONE : (910) 486-4864
PHONE : (910) 486-4864

DIRECTIONS : T/S: 11/21/2012 11:51 AM JBROCK ----
TAKE HWY 27 TO DOCS RD TURN LEFT GO
ABOUT 1.5 MILES TURN LEFT INTO S/D LOT
33

STRUCTURE: 000 000 61X36 4BDR SALB W/ GARAGE & SLAB

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4000000.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/05/13	MR	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002335057
	2/05/13	AP	T/S: 02/05/2013 12:43 PM MREARIC -----
A814 01	2/08/13	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002337053
B103 01	2/08/13 <u>2-8-13</u>	TI <u>AP-MR</u>	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002337046

COMMENTS AND NOTES