

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: X **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: R-3

Name: Wyuu Construction, Inc.

Address: 37 Triple Crown Ct.

Permit Numbers

Building: 13-50030515

Electrical: 11

Insulation: 11

Plumbing: 11

Mechanical: 11

MFG Home:

Date: 10-2-13

Building Official: T. Michael Reavis

ADDRESS : 37 TRIPLE CROWN CT
 CONTRACTOR : WYNN CONSTRUCTION, INC.
 OWNER : HARNETT DEVELOPERS LLC
 PARCEL : 03-0507- - -0200- -58-
 APPL NUMBER: 13-50030515 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 01/29/2013 11:55 AM JBROCK ----
 HWY 27 TO DOCS RD LEFT ON DOCS RD S/D
 ON THE R LOT 69

SUBDIV: TROTTERS RIDGE PHASE2A
 PHONE : (919) 528-1347
 PHONE :

STRUCTURE: 000 000 56X66 4BDR MONO W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4000000.00
 SEPTIC - EXISTING? : NEW
 PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	7/09/13	MR	R*PLUMB UNDER SLAB VRU #: 002407112
	7/09/13	AP	T/S: 07/09/2013 03:06 PM MREARIC -----
A814 01	7/10/13	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002408094
	7/10/13	AP	37 triple crown ct lillington 27546 ----- T/S: 07/10/2013 01:47 PM TWARD -----
B114 01	7/10/13	MR	R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 002408102
	7/10/13	AP	T/S: 07/10/2013 02:21 PM MREARIC -----
B104 01	8/05/13	JB	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 002420784
	8/05/13	AP	T/S: 08/05/2013 08:22 AM JBROCK -----
R425 01	8/08/13	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002420792
	8/08/13	DA	T/S: 08/08/2013 01:38 PM MREARIC ----- plmb tests too low / ok to side and insul.
R425 02	8/15/13	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002425833
	8/15/13	AP	ROUGH IN INSPECTION TO LOOK AT WHAT DID NOT PASSED AND TO REDO THE ELE DUE TO HE WIRES BEING STOLEN OUT OF THE HOUSE T/S: 08/15/2013 02:26 PM MREARIC -----
I129 01	8/21/13	MR	R*INSULATION INSPECTION VRU #: 002427904
	8/21/13	DA	T/S: 08/21/2013 01:32 PM MREARIC ----- insulation strip missing over master bathe area, ok to drywall , it can be seen from attic
R125 01	9/03/13	MR	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002434041
	9/03/13	AP	wire stone inspection - customer paid - T/S: 09/03/2013 01:59 PM MREARIC ----- wire
E209 01	9/23/13	MR	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002442317
	9/23/13	AP	T/S: 09/23/2013 01:39 PM MREARIC ----- #08048379
H824 01	9/23/13	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002445047
	9/23/13	AP	T/S: 09/25/2013 04:42 PM SSTEWARD ----- T/S: 09/25/2013 04:42 PM SSTEWARD -----
R429 01	10/02/13	TI	FOUR TRADE FINAL VRU #: 002447175
	10/02/13	AP-MR	
I129 02	10/02/13	TI	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002447209
	10/02/13	AP-MR	this needed to be put back on pre mike - it was ok to finish house, issue could be seen from attic

COMMENTS AND NOTES