Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Available Space (.1945) System Type(s)

Site LTAR

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Location Water Evaluation Type of		Auge	Dat	te Evaluated: sign Flow (.1949): perty Recorded: Individual Pit Industrial	Well ☐ Sprin	ng 🔲 Othe	er		
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	MORPHOLOGY .1941 .1941 Consistence Mineralogy	OTHER PROFILE FACTORS .1942 Soil .1943 .1956 .1944 Wetness/ Soil Sapro Restr Color Depth (IN.) Class Horiz				Profile Class & LTAR
١	とり	0 12%		n (en say) P				8,3
J.		०५४	65	VFO NAV					7.
		1					A comment		
		-							
		:			·				
Description Initial Repair System System Available Space (.1945) Repair System Other Factors (.1946): Site Classification (.1948): Evaluated By:									
Available Space (.1945) Evaluated By:									

Others Present: