Divis	artment of En sion of Enviro Site Wastewat	onmental I		tural Resources		Sheet: Property ID: Lot #: File #:			•
	for ON-		ITE EVALUAT ASTEWATER S			Code:			
Locat Wate Evalu		l: 🚺 Aug	Prop	🔲 Pit	Well	Oth	er		
P R O F I	.1940		SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
	6544.	0.24	6/56	VENSNP					
		24-41	59K 5EI	VENINP FrSSSP			· · ·		PS.55-4
		6-41	GBL	VATINTAL					
		41-40	53 K/5CI	VARNSNA FRISSP					Ø.5
		G -29	G/51	SGNSNE					
				Frisp					8.5
								· · · · · · · · · · · · · · · · · · ·	
Deserie		Te							

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948): <i>DJ</i>
Available Space (.1945)			Evaluated By: Br
System Type(s)	257-	25%	Others Present:
Site LTAR	15	.5	