

PARCEL NUMBER : 09-9567- - -0054- -26-
 Property address : 103 DINO CT
 Appl, structure nbr : 13 50031020 000 000
 Permit type, seq nbr : CPSF 00 CP * SFD
 Inspection type, seq nbr : R325 0001 THREE TRADE ROUGH IN
 Inspection status, date : INSPECTION COMPLETED 9/10/15

09

Inspection Results Comments

1-COULD NOT VERIFY ANCHOR BOLTS IN GARAGE 2-GARAGE DOOR
 STRAPING NOT INSTALLED. 3-STRAP ALL COLOUMS OF MORE THAN 3
 4-NEED INFO ON WINDOW AND DOOR HEADERS. 5-ROOF BOOTS
 MISSING. 6-HOUSE NEEDS FIRE CHALK AND BLOCKING IN SEVERAL
 AREAS. 7-DUCT CHASE PANTY/KITCHEN REQUIRES FIRE BLOCK
 8-SHOWER PAN TEST NOT INSTALLED. 9-STRAP COLOUMS ON STAIRS
 10-STRAP AND TIE NON CONNECTED ANGLED TOP PLATES ON BAY AND
 OTHER WALLS. 11-FRONT DOOR HEADER NEEDS VERIFYING ALSO JACK
 STUDS COUNT. 12-ALL REQUIRED AIR BARRIERS NEED TO BE SEALED

More...

Press Enter to continue.
 F3=Exit F12=Cancel

Harnett County
Inspection Inquiry - Results Comments

1/04/16
08:53:57

PARCEL NUMBER	:	09-9567- - -0054- -26-	
Property address	:	103 DINO CT	
Appl, structure nbr	:	13 50031020 000 000	09
Permit type, seq nbr	:	CPSF 00 CP * SFD	
Inspection type, seq nbr	:	R325 0001 THREE TRADE ROUGH IN	
Inspection status, date	:	INSPECTION COMPLETED	9/10/15

Inspection Results Comments

PROPERLY AND REPAIRED. 13-DRYER DUCT LENGTH NOT LABELED.
 14- SIDING NOT COMPLETE 15-SEVERAL WINDOWS AND DOORS ON
 REAR NOT SEALED. 16-FIREPLACE NOT INSTALLED COMPLETE. STOPPED
 DID NOT COMPLETE INSPECTION OF CRAWL SPACE AND ALL LOAD
 BEARING POINTS PER PLAN

T/S: 09/10/2015 10:50 AM SGUY -----

Press Enter to continue.
F3=Exit F12=Cancel

Bottom