Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Description

Available Space (.1945) System Type(s) Site LTAR Initial

System

Pund

Repair System

Sheet:
Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Address: Proposed Facility: Location of Site: Water Supply: Evaluation Method Type of Wastewate		Public Individual Well Spring Other							
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,2	L-5%	0-10	<i>د</i>	FUGNUSWP					
		10-36	X-CIAY	ENGRASHP ENGRASHS.R CHERNSHI ENTERNSHI	30-32 703		······································		.3
3,4,5	L-52	6-12	5L	en 6n vin			***		
		12-40	sicing f	ent ENCS.P.	32.17045		-		. 3
			,		,				
	*								- · · · · · · · · · · · · · · · · · · ·

Other Factors (.1946):

Site Classification (.1948):

Others Present:

Evaluated By: