Department of Environment, Health and Natural Resources
Division of Environmental Health
On-Site Wastewater Section

Sheet:
Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner: Applicant:
Address: Date Evaluated: 4/26/13
Proposed Facility: 6 Bedroom Design Flow (.1949): 720 gpd Property Size:
Location of Site: Property Recorded:
Water Supply: ☒ Public ☐ Individual ☐ Well ☐ Spring ☐ Other
Evaluation Method: ☒ Auger Boring ☐ Pit ☐ Cut
Type of Wastewater: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	
1	LS 3-7	0-24"	G S	VFR NS/NP					
		24-30	G SL	VFR NS/NP					PS .65
		30-48	G S	VFR NS/NP					
2		0-48	G S	VFR NS/NP					S .8
3		0-42	G S	VFR NS/NP					
		42-48	G SL	VFR NS/NP					PS .65

Description	Initial System ✓	Repair System ✓
Available Space (.1945)		
System Type(s)	25%	Pump
Site LTAR	.65	.65

Other Factors (.1946):
Site Classification (.1948): S
Evaluated By: [illegible]
Others Present: —

1350 gal tank = 1500