Divis On-S Owne Addre	ion of Envirc ite Wastewat for ON- er:	onmental H er Section SOIL/SI	TE EVALUAT STEWATER S t: Date	TION	Property	Sheet: Property ID: Lot #: File #: Code: Property Size:			
Water Evalu Type	ion of Site: Supply: ation Method of Wastewate	l: Auge er:	Prop	erty Recorded:	Well	ng 🗌 Oth	er		
P R O F I L E #	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY		OTHER PROFILE FACTORS .1942				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
	1557,	0-48	G/15	S FNNSNP			•		5.8
		0-48	c/15	V GWSNP					5.8
		C-48	G/LS	She NINP					5.8
			<u></u>				an a statement of the second se		
					<u></u>			-	

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)			Evaluated By?
System Type(s)	25%	256.	Others Present:
Site LTAR	. 8	.0	