

**COUNTY OF HARNETT**  
**Building Inspections Department**  
**Planning Services**

**Certificate of Compliance:** \_\_\_\_\_ **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Robert Pape

Address: 503 Turlington Rd  
Dunn, NC 28334

Date: 3-10-14

Building Official: \_\_\_\_\_

*D. E. E. E.*

**Permit Numbers**

Building: \_\_\_\_\_  
Electrical: \_\_\_\_\_  
Insulation: \_\_\_\_\_  
Plumbing: \_\_\_\_\_  
Mechanical: \_\_\_\_\_  
MFG Home: \_\_\_\_\_

*13-50031907*

ADDRESS : 503 TURLINGTON RD SUBDIV:  
 CONTRACTOR : POPE ROBERT PHONE : (919) 868-2912  
 OWNER : ENNIS DONALD & LAURA PHONE :  
 PARCEL : 07-1509- - -0023- -02-  
 APPL NUMBER: 13-50031907 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: T/S: 08/09/2013 09:34 AM JBROCK ----  
 HWY 421 TO HWY 55 R TOWARD COATS L ONTO  
 TURLINGTON 1/2 MILE L ONTO JOB

**STRUCTURE: 000 000 61X46 3BDR CRAWL W/ GARAGE & DECK**

FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3000000.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/17/13 9/17/13	BS DA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002440238 T/S: 09/16/2013 12:21 PM VBROWN ----- T/S: September 17, 2013 09:53 AM BSUTTON ----- Lug footings missing around garage
B101 02	9/18/13 9/18/13	BS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002441186 T/S: 09/17/2013 02:36 PM VBROWN ----- T/S: September 18, 2013 08:01 AM BSUTTON -----
A814 01	9/24/13 9/24/13	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002443885 503 Turlington Rd Dunn 28334 T/S: 09/24/2013 11:48 AM TWARD -----
B103 01	9/25/13 9/25/13	DT AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 002443396 VOICE MESSAGE LEFT T/S: 09/25/2013 10:49 AM DETAYLOR -----
B105 01	9/30/13 9/30/13	DT AP	R*OPEN FLOOR TIME: 17:00 VRU #: 002446250 T/S: 09/30/2013 11:05 AM DETAYLOR -----
R425 01	10/31/13 10/31/13	DT DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002460004 T/S: 10/30/2013 02:08 PM DJOHNSON ----- T/S: 10/31/2013 03:16 PM DETAYLOR ----- Missing air barrier behind spare tub Okay to side and insulate
I129 01	11/05/13 11/05/13	DT AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002461044 T/S: 11/05/2013 02:10 PM DETAYLOR -----
R425 02	11/05/13 11/05/13	DT AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002461051 T/S: 11/05/2013 02:10 PM DETAYLOR -----
E209 01	2/28/14 2/28/14	DT AP	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002497980 T/S: 02/28/2014 03:28 PM DETAYLOR -----
R429 01	3/10/14 <u>3/10/14</u>	TI <u>AP DT</u>	FOUR TRADE FINAL TIME: 17:00 VRU #: 002501062 OP PERMIT WAS DONE 3/7/14 BY JAMES M.

COMMENTS AND NOTES