

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: X **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: R-3

Name: Stawell Builders

Address: 25 ALPINE DR

Date: 11-3-15

Building Official: C. McLaughlin

Permit Numbers

Building: 13-50032052

Electrical: 11

Insulation: 11

Plumbing: 11

Mechanical: 11

MFG Home:

ADDRESS : 25 ALPINE DR SUBDIV:
 CONTRACTOR : STANCIL BUILDERS INC. PHONE : (919) 639-2073
 OWNER : STANCIL BUILDERS INC PHONE :
 PARCEL : 03-9587-01- -0020- -01-
 APPL NUMBER: 13-50032052 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : T/S: 09/04/2013 01:52 PM JBROCK ----
 SUNSET RIDGE #1R

STRUCTURE: 000 000 52X33 3BDR CRAWL W/ GARAGE & DECK
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/02/13	MR	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002447894
	10/02/13	AP	T/S: 10/02/2013 01:27 PM MREARIC
B103 01	10/23/13	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 002456176
	10/23/13	AP	T/S: 10/23/2013 02:43 PM MREARIC
B105 01	4/03/14	MR	R*OPEN FLOOR VRU #: 002510991
	4/03/14	AP	T/S: 04/03/2014 02:03 PM MREARIC
A814 01	5/21/14	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002530608
	5/21/14	DA	25 ALPINE DR BROADWAY 27505
			T/S: 05/21/2014 03:49 PM TWARD
			T/S: 05/21/2014 03:49 PM TWARD
			T/S: 01/20/2015 01:24 PM TWARD
R425 01	5/22/14	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002530616
	5/22/14	CA	T/S: 05/20/2014 02:03 PM VBROWN
			T/S: 05/22/2014 08:22 AM LSEGARS
R425 02	6/13/14	MR	FOUR TRADE ROUGH IN VRU #: 002540977
	6/13/14	DA	T/S: 06/13/2014 01:33 PM MREARIC
			air barriers are needed at fireplace
			no water pressure
			need tempered window at top of stairs
R425 03	7/16/14	MR	FOUR TRADE ROUGH IN VRU #: 002555087
	7/16/14	AP	T/S: 07/16/2014 09:56 AM MREARIC
I129 01	7/21/14	MR	R*INSULATION INSPECTION VRU #: 002556727
	7/21/14	AP	T/S: 07/21/2014 12:47 PM MREARIC
H824 01	8/05/14	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002563849
	8/05/14	AP	T/S: 08/06/2014 09:57 AM SSTEWARD
			T/S: 08/06/2014 09:57 AM SSTEWARD
A814 02	1/21/15	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002619484
	1/21/15	AP	25 ALPINE DR
			SANFORD, NC 27332
			**PREVIOUSLY GIVEN AN INCORRECT CITY OF BROADWAY 27505
			T/S: 01/21/2015 08:20 AM TWARD
R429 01	3/05/15	TSG	FOUR TRADE FINAL TIME: 17:00 VRU #: 002631042
	3/05/15	AE	T/S: 03/04/2015 12:25 PM DJOHNSON
			1-SECOND FLOOR WINDOWS MISSING CHILD LOCKS 2-WALL LEFT SIDE
			ATTIC ENTRANCE MISSING AIR BARRIER.
R429 02	11/03/15	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002737575

11 AP-MR

COMMENTS AND NOTES