

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Stancel Builders Inc

Address: 51 Alvis Ct
Fuquay Varina, NC 27526

Date: 7-17-14

Building Official: [Signature]

Permit Numbers

Building: _____

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: 1350032224

MFG Home: _____

ADDRESS : 51 ALVIS CT SUBDIV: DEXTERFIELD
CONTRACTOR : STANCIL BUILDERS INC. PHONE : (919) 639-2073
OWNER : STANCIL BUILDERS INC PHONE :
PARCEL : 08-0653- - -0030- -56-
APPL NUMBER: 13-50032224 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 10/02/2013 03:02 PM VBROWN ----
ALVIS COURT, DEXTERFIELD SUB DIV #56

STRUCTURE: 000 000 48X42 3BDR 2BATH SFD W GAR DECK CRAWL

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/27/14 3/27/14	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002507736 T/S: March 27, 2014 10:14 AM BSUTTON ----- One t pole for two lots, waiting for premise number.
B103 01	4/04/14 4/04/14	MR AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 002511455 T/S: 04/04/2014 02:19 PM MREARIC -----
B105 01	4/11/14 4/11/14	BS AP	R*OPEN FLOOR VRU #: 002514636 T/S: April 11, 2014 09:20 AM BSUTTON -----
A814 01	4/11/14 4/16/14	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002514610 51 alvis ct fuquay varina 27526 T/S: 04/16/2014 02:29 PM TWARD -----
R425 01	5/05/14 5/05/14	BS DP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002523074 T/S: 05/02/2014 12:35 PM DJOHNSON ----- T/S: May 05, 2014 10:57 AM BSUTTON ----- Framing at garage door incomplete. Front door missing. No firestop done. Inspection stopped. \$50 re fee
R425 02	5/07/14 5/06/14	TI CA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002524130 T/S: 05/06/2014 10:49 AM LSEGARS -----
R425 03	5/12/14 5/12/14	BS DA	FOUR TRADE ROUGH IN VRU #: 002526047 T/S: May 12, 2014 08:17 AM BSUTTON ----- No water test on drain system. 2. Nut and washer missing in garage. 3.Improper uplift on girder truss in garage. 4.Roof beams at rear porch must either be cut into house on jack studs, or a support post must be underneath. Ok to side/insulate
I129 01	5/14/14 5/14/14	BS AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002527281 T/S: 05/13/2014 10:17 AM VBROWN ----- T/S: May 14, 2014 09:27 AM BSUTTON -----
R425 04	5/14/14 5/14/14	BS AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002527299 T/S: 05/13/2014 10:17 AM VBROWN ----- T/S: May 14, 2014 09:27 AM BSUTTON -----
H824 01	6/09/14 6/09/14	JM AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002540169 T/S: 06/11/2014 10:57 AM SSTEWARD ----- T/S: 06/11/2014 10:57 AM SSTEWARD -----
R429 01	7/15/14 7/15/14	DT DA	FOUR TRADE FINAL TIME: 17:00 VRU #: 002554236 T/S: 07/14/2014 10:02 AM VBROWN ----- T/S: 07/15/2014 10:31 AM DETAYLOR ----- Need energy efficiency certificate Need Co detectors outside bedrooms eed premiss number for power

PREPARED 7/16/14, 14:19:20
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 5
DATE 7/17/14

ADDRESS : 51 ALVIS CT
CONTRACTOR : STANCIL BUILDERS INC.
OWNER : STANCIL BUILDERS INC
PARCEL : 08-0653- - -0030- -56-
APPL NUMBER: 13-50032224 CP NEW RESIDENTIAL (SFD)

SUBDIV: DEXTERFIELD
PHONE : (919) 639-2073
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R429 02	7/17/14 <i>7/17/14</i>	TI <i>AS</i>	FOUR TRADE FINAL TIME: 17:00 VRU #: 002555449 T/S: 07/16/2014 09:52 AM LSEGARS PREMISE # 48282383

COMMENTS AND NOTES