Divisi On-Si Owne Addre Propo Locati Water Evalua	ion of Envirc ite Wastewate for ON- r:	nmental H er Section SOIL/SI SITE WA Applican 3 9 0	ITE EVALUAT STEWATER S ht: Date Date Prope Prope	ION YSTEM Evaluated: n Flow (.1949): 3/ rty Recorded:	Well Spring Other				· •
P R O F I L E #	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	LS 0-2		0-28	GS	VED 43 Erp				
			28-42	58X 5CL	57 55 50				85,4
٩			0-29	G 5	VFA NSWO FA SSI-P				
<u></u>			29-42	SBKSLL	Fr ssl-p				P5 . L1
			· · · ·						
									· · · · · · · · · · · · · · · · · · ·
								i	

Description	Initial	Repair System	Other Factors (.1946):
	System/	,	Site Classification (.1948): (15)
Available Space (.1945)	V	\checkmark	Evaluated By: \bigcirc \checkmark
System Type(s)	23%	REO	Others Present: Kon
Site LTAR	L	. 1-1	

3>75 618-30