

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Stancil Builders Inc

Address: 135 Oxfordshire Dr
Fuquay-Varina, NC 27526

Date: 8-13-14

Building Official: _____

[Signature]

Permit Numbers

Building: _____

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: 1350032300

MFG Home: _____

ADDRESS : 135 OXFORDSHIRE DR SUBDIV: HADDEN POINTE 40LOTS
 CONTRACTOR : STANCIL BUILDERS INC. PHONE : (919) 639-2073
 OWNER : STANCIL BUILDERS INC. PHONE :
 PARCEL : 08-0652- - -0024- -11-
 APPL NUMBER: 13-50032306 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 10/14/2013 08:41 AM JBROCK ----
 HADDEN POINTE #6 **77271445**

STRUCTURE: 000 000 42X40 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/28/14	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002508655
	3/28/14	AP	T/S: March 28, 2014 10:08 AM BSUTTON -----
B103 01	4/22/14	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 002517743
	4/22/14	AP	T/S: April 22, 2014 08:56 AM BSUTTON -----
A814 01	4/22/14	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002517752
	4/30/14	AP	135 oxfordshire dr fuquay varina 27526 ----- T/S: 04/30/2014 04:58 PM TWARD -----
B105 01	5/05/14	BS	R*OPEN FLOOR VRU #: 002522951
	5/05/14	AP	T/S: May 05, 2014 09:15 AM BSUTTON -----
R425 01	5/22/14	BS	FOUR TRADE ROUGH IN VRU #: 002531102
	5/22/14	DA	T/S: May 22, 2014 08:58 AM BSUTTON ----- Remove fireplace and cover insulation with a rigid material. 2. Foundation access must be 18x36 minimum. Ok to side/insulate
R425 02	5/27/14	BS	FOUR TRADE ROUGH IN VRU #: 002532316
	5/27/14	AP	T/S: May 27, 2014 11:45 AM BSUTTON -----
I129 01	6/04/14	BS	R*INSULATION INSPECTION VRU #: 002536544
	6/04/14	DA	T/S: June 04, 2014 09:10 AM BSUTTON ----- insulation must be changed to R13 and R38
I129 02	6/10/14	BS	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002538882
	6/10/14	AP	T/S: 06/09/2014 08:56 AM VBROWN ----- T/S: June 10, 2014 01:13 PM BSUTTON -----
H824 01	6/11/14	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002540896
	6/11/14	AP	T/S: 06/12/2014 11:40 AM SSTEWARD ----- T/S: 06/12/2014 11:40 AM SSTEWARD -----
R429 01	8/13/14	TI	FOUR TRADE FINAL VRU #: 002566501
	<u>8/13/14</u>	<u>ARD</u>	

COMMENTS AND NOTES