Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Applicant:

Owner:

Description

System Type(s) Site LTAR

Available Space (.1945)

Initial

System

05 20 1000

Repair System

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Locatio Water Evalua	ed Facility:	Auge	Date I Design	Evaluated: n Flow (.1949): \frac{1}{2}\text{V} rty Recorded: dividual	Vell Spring		er		,
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	25	0.24	65	VALUE MA					
		24	58 X SCL	FOC 55/18					P5.5
2		0.N	60	VFRAGNA FRESS/NA					0.5
		19-36	SBKSCL	FT 55/14					15
3		0.30	65	VFO relab					
		30	SBX SCL	नि श्रीभ					P35
									i a
					×				

Other Factors (.1946): Site Classification (.1948):

Others Present:

Evaluated By:

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	<u>TEXTURES</u>	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET	
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE	П	S-SAND LS-LOAMY SAND SL-SANDY LOAM L-LOAM SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	1.2 - 0.8 0.8 - 0.6	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY	
N-NOSE SLOPE H-HEAD SLOPE CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш		0.6 - 0.3		VS-VERY STICKY NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC	

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB

MINERALOGY SLIGHTLY EXPANSIVE

GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

EXPANSIVE

PL-PLATY PR-PRISMATIC

Show profile locations and other site features (dimensions, references or benchmark, and North)

