

ADDRESS : 145 BISON LN
 CONTRACTOR : H & H CONSTRUCTORS INC
 OWNER : H & H CONSTRUCTORS INC
 PARCEL : 03-0507- - -0046- -54-
 APPL NUMBER: 13-50032672 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 12/23/2013 03:43 PM JBROCK ----
 OAKMONT #138

SUBDIV: OAKMONT PH1 SECT2 25LOTS
 PHONE : (910) 486-4864
 PHONE :

STRUCTURE: 000 000 53X56.6 4BDR CRAWL W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4000000.00
 SEPTIC - EXISTING? : NEW TANK
 PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS	TIME	VRU #
B101 01	1/21/14	MR	R*BLDG FOOTING / TEMP SVC POLE	17:00	002486157
	1/21/14	AP	T/S: 01/21/2014 12:32 PM MREARIC		
A814 01	1/23/14	TW	ADDRESS CONFIRMATION	17:00	002486975
	1/28/14	AP	145 BISON LN LILLINGTON 27546		
			T/S: 01/28/2014 10:11 AM TWARD		
B103 01	1/23/14	MR	R*BLDG FOUND & TEMP SVC POLE	17:00	002486967
	1/23/14	AP	T/S: 01/23/2014 02:10 PM MREARIC		
B105 01	1/24/14	MR	R*OPEN FLOOR	17:00	002487783
	1/24/14	AP	T/S: 01/24/2014 02:10 PM MREARIC		
E207 01	2/03/14	MR	R*ELEC TEMP SERVICE POLE	17:00	002489946
	2/03/14	AP	pole needs to be checked		
			T/S: 02/03/2014 01:23 PM MREARIC		
B104 01	2/20/14	JB	R*FOUND & SETBACK VERIF SURVEY	17:00	002495182
	2/20/14	AP	T/S: 02/20/2014 01:45 PM JBROCK		
R425 01	2/21/14	MR	FOUR TRADE ROUGH IN	17:00	002495190
	2/21/14	AE	T/S: 02/21/2014 01:33 PM MREARIC		
			2 windows missing / ok to insulate but not side		
I129 01	2/25/14	FS	R*INSULATION INSPECTION	17:00	002496347
	2/25/14	AP	T/S: 02/25/2014 02:57 PM FSPIVEY		
H824 01	3/11/14	OT	ENVIR. OPERATIONS PERMIT	17:00	002502532
	3/11/14	AP	T/S: 03/12/2014 02:19 PM SSTEWARD		
			T/S: 03/12/2014 02:19 PM SSTEWARD		
E209 01	3/27/14	DT	R*ELEC TEMP POWER CERT	17:00	002508091
	3/27/14	AP	T/S: 03/27/2014 12:31 PM DETAYLOR		
R429 01	5/29/14	TI	FOUR TRADE FINAL	17:00	002533750

11 AP-MR

COMMENTS AND NOTES