

**SOIL/SITE EVALUATION
 for ON-SITE WASTEWATER SYSTEM**

Owner: Applicant: *mms*
 Address: Date Evaluated: *7-15-17-14*
 Proposed Facility: *seo* Design Flow (.1949): *360* Property Size:
 Location of Site: Property Recorded:
 Water Supply: Public Individual Well Spring Other
 Evaluation Method: Auger Boring Pit Cut
 Type of Wastewater: Sewage Industrial Process Mixed

| P R O F I L E # | .1940 Landscape Position/ Slope % | Horizon Depth (In.) | SOIL MORPHOLOGY .1941 | | OTHER PROFILE FACTORS | | | | Profile Class & LTAR |
|--------------------------------------|--|---------------------------|--------------------------------|------------------------------------|------------------------------------|------------------------------|-------------------------|-------------------------|----------------------------|
| | | | .1941 Structure/ Texture | .1941 Consistence Mineralogy | .1942 Soil Wetness/ Color | .1943 Soil Depth (IN.) | .1956 Sapro Class | .1944 Restr Horiz | |
| 1 | <i>L-3-48</i> | <i>0-18</i> | <i>SL</i> | <i>fin GR SAND</i> | | | | | |
| | | <i>18-44</i> | <i>SCL</i> | <i>fin. 1/2" S.P.</i> | <i>42-44" 2.5% 3.1</i> | | | | <i>.4</i> |
| 2 | <i>L-3-48</i> | <i>0-15</i> | <i>SL</i> | <i>fin GR SAND</i> | | | | | |
| | | <i>15-44</i> | <i>SCL</i> | <i>fin 1/2" S.P.</i> | <i>40-42 2.5% 3.1</i> | | | | <i>.4</i> |
| 3 | <i>L-3-48</i> | <i>0-24</i> | <i>SL</i> | <i>fin GR SAND</i> | | | | | |
| | | <i>24-42</i> | <i>SCL</i> | <i>fin 1/2" S.P.</i> | <i>40" 2.5% 3.1</i> | | | | <i>.4</i> |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| | | | |
|-------------------------|----------------|---------------|---|
| Description | Initial System | Repair System | Other Factors (.1946): Site Classification (.1948): Evaluated By: <i>[Signature]</i> Others Present: |
| Available Space (.1945) | <i>/</i> | <i>/</i> | |
| System Type(s) | <i>28"</i> | <i>28"</i> | |
| Site LTAR | <i>.4</i> | <i>.4</i> | |