

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Bill Clark Homes LLC

Address: 27 Shortleaf Ct
Cameron, NC 28326

Date: 1-21-16

Building Official: [Signature]

Permit Numbers

Building: _____


Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: 14-50034575

MFG Home: _____



ADDRESS : 27 SHORTLEAF CT
CONTRACTOR : BILL CLARK HOMES LLC
OWNER : BILL CLARK HOMES OF FAYETTEVILLE
PARCEL : 09-9567-03- -0006- -31-
APPL NUMBER: 14-50034575 CP NEW RESIDENTIAL (SFD)

SUBDIV: CAROLINA SEASONS PH2 SECT 2 59
PHONE : (252) 355-5805
PHONE :

DIRECTIONS : T/S: 09/09/2014 08:33 AM JBROCK ----
CAROLINA SEASONS #88

STRUCTURE: 000 000 36.10X60 4BDR CRAWL W/ GARAGE & PATIO

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4000000.00
SEPTIC - EXISTING? : NEW TANK
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/30/15 6/30/15	TSG AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002680842
A814 01	7/17/15 7/17/15	SB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002689263 27 SHORTLEAF CT CAMERON 28326 T/S: 07/17/2015 09:25 AM SBENNETT -----
B103 01	7/17/15 7/17/15	MR AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002689255 T/S: 07/16/2015 11:44 AM LBENNETT ----- T/S: 07/17/2015 02:13 PM MREARIC -----
P309 01	7/31/15 7/31/15	TSG DA	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002697175 T/S: 07/30/2015 12:05 PM KGOINS ----- FOUNDATION INSULATION REMOVED AND NOT REPAIRED AT PLUMBING PENETRATION.
P309 02	8/05/15 8/05/15	TSG AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002698686 T/S: 08/04/2015 11:44 AM LBENNETT -----
B111 01	8/10/15 8/10/15	TSG DA	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002700524 T/S: 08/07/2015 10:28 AM LBENNETT ----- 1- LEFT SIDE THICKENED FOOTER DOES NOT EXTEND THE LENGTH MEASURED ON PLANS FOR THE LOAD BEARING WALL AS THE FOOTER NEXT TO IT. 2- LUG FOOTER INDICATED ON PLANS FOR LAUNDRY AREA IS MISSING.
B111 02	8/11/15 8/11/15	TSG AP	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002701860 T/S: 08/11/2015 08:28 AM LBENNETT -----
R425 01	10/01/15 10/01/15	TSG DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002725521 T/S: 09/30/2015 11:44 AM LBENNETT ----- 1- ATTACH INTERIOR LOAD BEARING WALLS 2-STRAP COLOUM AT LVL IN KITCHEN 3-HEAD TEST DOWN 4-REPAIR AIR BARRIER OVER GARAGE.
I129 01	10/06/15 10/06/15	TSG AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002726271
R425 02	10/06/15 10/06/15	TSG AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002726263
H824 01	10/14/15 10/14/15	BM DA	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002730497 PER BRYAN MCSWAIN OPERATIONS PERMIT ON HOLD FOR PUMP, ALARM, D-BOX, AND CHECK SANITARY-T. ALL TO BE INSPECTED BEFORE IT CAN BE ISSUED. CALL HIM WHEN READY 893-7547. T/S: 10/14/2015 04:55 PM SSTEWARD -----
E209 01	1/21/16	DT	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002767762

PREPARED 1/21/16, 14:44:16
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 2
DATE 1/21/16

ADDRESS : 27 SHORTLEAF CT
CONTRACTOR : BILL CLARK HOMES LLC
OWNER : BILL CLARK HOMES OF FAYETTEVIL
PARCEL : 09-9567-03- -0006- -31-
APPL NUMBER: 14-50034575 CP NEW RESIDENTIAL (SFD)

SUBDIV: CAROLINA SEASONS PH2 SECT 2 59
PHONE : (252) 355-5805
PHONE :

REQUESTED INSP DESCRIPTION
TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

1/21/16 AP T/S: 01/20/2016 12:16 PM DJOHNSON -----
T/S: 01/21/2016 02:22 PM DETAYLOR -----
R429 01 1/21/16 TI FOUR TRADE FINAL TIME: 17:00 VRU #: 002768349
1-21-16 AP DT


----- COMMENTS AND NOTES -----

New Installation Septic Tank Nitrification Line Repair Expansion

(owner) Bill Clark Homer PROPERTY LOCATION: Ponderosa Rd
 m. Installer: Jones Septic SUBDIVISION: Caroline Seasons LOT # 88
 Registration # _____

ment with plumbing: Garage Number of Bedrooms: 4
 of Water Supply: Community Public Well Distance from well: _____ feet
 m Type: III b Types V and VI Systems expire in 5 years.
 accordance with Table V a) Owner must contact Health Department 6 months prior to expiration for permit renewal.

system has been installed in compliance with applicable North Carolina General Statutes, Rules for Sewage Treatment and Disposal, and all conditions of the Improvement Permit and Construction Authorization.



PERMIT CONDITIONS:
 I. Performance: System shall perform in accordance with Rule 1961.
 II. Monitoring: As required by Rule 1961.
 III. Maintenance: As required by Rule 1961. Other: _____
 Subsurface system operator required? Yes No
 If yes, see attached sheet for additional operation conditions, maintenance, and reporting.

IV. Operation: _____
 V. Other: _____
 Pump Alarm H2O Line

Following are the specifications for the sewage disposal system on the above captioned property:
 Type of system: Conventional Other Compto. Quick Chamber Septic Tank: 1000 gallons Pump Tank: 1000
 Subsurface: _____ width of ditches: 3 feet depth of ditches: 24-30 in.
 Drainage Field: _____ exact length of each ditch: 80 feet
 French-Drain Required: _____ No. of ditches: 3 Linear feet

Date: 1/21/16

Authorized State Agent: _____

ADDRESS : 27 SHORTLEAF CT SUBDIV: CAROLINA SEASONS PH2 SECT 2 59
 CONTRACTOR : BILL CLARK HOMES LLC PHONE : (252) 355-5805
 OWNER : BILL CLARK HOMES OF FAYETTEVILLE PHONE :
 PARCEL : 09-9567-03- -0006- -31-
 APPL NUMBER: 14-50034575 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 09/09/2014 08:33 AM JBROCK ----
 CAROLINA SEASONS #88

STRUCTURE: 000 000 36.10X60 4BDR CRAWL W/ GARAGE & PATIO

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/30/15 6/30/15	TSG AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002680842
A814 01	7/17/15 7/17/15	SB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002689263 27 SHORTLEAF CT CAMERON 28326 T/S: 07/17/2015 09:25 AM SBENNETT -----
B103 01	7/17/15 7/17/15	MR AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002689255 T/S: 07/16/2015 11:44 AM LBENNETT ----- T/S: 07/17/2015 02:13 PM MREARIC -----
P309 01	7/31/15 7/31/15	TSG DA	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002697175 T/S: 07/30/2015 12:05 PM KGOINS ----- FOUNDATION INSULATION REMOVED AND NOT REPAIRED AT PLUMBING PENETRATION.
P309 02	8/05/15 8/05/15	TSG AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002698686 T/S: 08/04/2015 11:44 AM LBENNETT -----
B111 01	8/10/15 8/10/15	TSG DA	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002700524 T/S: 08/07/2015 10:28 AM LBENNETT ----- 1- LEFT SIDE THICKENED FOOTER DOES NOT EXTEND THE LENGTH MEASURED ON PLANS FOR THE LOAD BEARING WALL AS THE FOOTER NEXT TO IT. 2- LUG FOOTER INDICATED ON PLANS FOR LAUNDRY AREA IS MISSING.
B111 02	8/11/15 8/11/15	TSG AP	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002701860 T/S: 08/11/2015 08:28 AM LBENNETT -----
R425 01	10/01/15 10/01/15	TSG DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002725521 T/S: 09/30/2015 11:44 AM LBENNETT ----- 1- ATTACH INTERIOR LOAD BEARING WALLS 2-STRAP COLOUM AT LVL IN KITCHEN 3-HEAD TEST DOWN 4-REPAIR AIR BARRIER OVER GARAGE.
I129 01	10/06/15 10/06/15	TSG AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002726271
R425 02	10/06/15 10/06/15	TSG AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002726263
H824 01	10/14/15 10/14/15	BM DA	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002730497 PER BRYAN MCSWAIN OPERATIONS PERMIT ON HOLD FOR PUMP, ALARM, D-BOX, AND CHECK SANITARY-T. ALL TO BE INSPECTED BEFORE IT CAN BE ISSUED. CALL HIM WHEN READY 893-7547. T/S: 10/14/2015 04:55 PM SSTEWARD -----
E209 01	1/21/16 1/21/16	TI AP	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002767762 T/S: 01/20/2016 12:16 PM DJOHNSON -----

----- COMMENTS AND NOTES -----