

**COUNTY OF HARNETT**  
**Building Inspections Department**  
**Planning Services**

**Certificate of Compliance:** \_\_\_\_\_ **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Bill Clark Homes LLC

Address: 35 Knotty Pine Dr  
Cameron, NC 28326

Date: 1-21-16

Building Official: D. E. [Signature]

**Permit Numbers**

Building: \_\_\_\_\_

Electrical: \_\_\_\_\_


Insulation: \_\_\_\_\_

Plumbing: \_\_\_\_\_

Mechanical: 14 \_\_\_\_\_

MFG Home: \_\_\_\_\_

50034602



ADDRESS : 35 KNOTTY PINE DR  
 CONTRACTOR : BILL CLARK HOMES LLC  
 OWNER : BILL CLARK HOMES OF FAYETTEVILLE  
 PARCEL : 09-9567-03- -0006- -22-  
 APPL NUMBER: 14-50034602 CP NEW RESIDENTIAL (SFD)

SUBDIV: CAROLINA SEASONS PH2 SECT 2 59  
 PHONE : (252) 355-5805  
 PHONE :

**STRUCTURE: 000 000 45X55 3 BR ATT GARAGE SLAB**

FLOOD ZONE : FLOOD ZONE X

# BEDROOMS : 3.00

SEPTIC - EXISTING? : NEW

PROPOSED USE : SFD

WATER SUPPLY : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/30/15	TSG	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002681002
	6/30/15	AP	
A814 01	7/17/15	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002689248
	7/17/15	AP	35 KNOTTY PINE DR CAMERON 28326 T/S: 07/17/2015 09:21 AM SBENNETT -----
B103 01	7/17/15	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002689230
	7/17/15	AP	T/S: 07/16/2015 11:42 AM LBENNETT ----- T/S: 07/17/2015 02:13 PM MREARIC -----
P309 01	7/31/15	TSG	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002697183
	7/31/15	DA	T/S: 07/30/2015 12:07 PM DJOHNSON ----- FOUNDATION INSULATION DAMAGED AND NOT PUT BACK IN PLACE AT PLUMBING FOUNDATION PENETRATIONS
P309 02	8/05/15	TSG	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002698710
	8/05/15	AP	T/S: 08/04/2015 11:49 AM LBENNETT -----
B111 01	8/10/15	TSG	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002700532
	8/10/15	DA	T/S: 08/07/2015 10:29 AM LBENNETT ----- REAR WALL DAMMAGED AND BEING REPAIRED
B111 02	8/11/15	TSG	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002701845
	8/11/15	AP	T/S: 08/11/2015 08:27 AM LBENNETT -----
B104 01	9/17/15	JB	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 002719888
	9/17/15	AP	T/S: 09/17/2015 10:28 AM JBRACK -----
R425 01	9/18/15	TSG	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002719896
	9/18/15	DA	1- attach interior load bearing walls 2- need anchor bolt at rt side garage /house entry door 3- nail truss tails over rear porch ok to side and isulate
I129 01	9/22/15	TSG	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002720852
	9/22/15	AP	T/S: 09/21/2015 10:11 AM LBENNETT -----
R425 02	9/22/15	TSG	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002720860
	9/22/15	AP	T/S: 09/21/2015 10:11 AM LBENNETT -----
H824 01	10/13/15	BM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002730026
	10/13/15	AP	T/S: 10/14/2015 10:54 AM SSTEWARD ----- T/S: 10/14/2015 10:54 AM SSTEWARD -----
R429 01	1/21/16	TT	FOUR TRADE FINAL TIME: 17:00 VRU #: 002767739
	1/21/16	AP DT	T/S: 01/20/2016 12:14 PM DJOHNSON -----

COMMENTS AND NOTES

