
ADDRESS : 286 WIDGEON WAY
CONTRACTOR : WEAVER DEVELOPMENT CO INC
OWNER : WEAVER DEVELOPMENT COMPANY INC
PARCEL : 13-0630- - -0096- -15-
APPL NUMBER: 15-50035478 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 02/10/2015 09:21 AM VBROWN -----
286 WIDGEON WAY LILLINGTON 27546.
THOMAS MANOR #13. OLD 421, RIGHT ON
WIDGEON WAY ALL THE WAY TO THE END OF
THE CUL DE SAC.

STRUCTURE: 000 000 52X47 3BDR 2BATH SFD

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW TANK
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/11/15	TSG	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002632990
	3/11/15	AP	
B103 01	3/18/15	TSG	R*BLDG FOUND & TEMP SVC POLE VRU #: 002636173
	3/18/15	AP	
A814 01	3/19/15	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002636181
	3/19/15	AP	286 WIDGEON WAY LILLINGTON 27546 POST # ON HOME T/S: 03/19/2015 09:31 AM SBENNETT -----
P309 01	3/20/15	MR	R*PLUMB UNDER SLAB VRU #: 002637023
	3/20/15	AP	
B111 01	3/24/15	TSG	T/S: 03/20/2015 02:35 PM MREARIC -----
	3/24/15	AP	R*BLDG SLAB INSP/TEMP SVC POLE VRU #: 002637882
R425 01	4/16/15	TSG	FOUR TRADE ROUGH IN VRU #: 002647261
	4/16/15	DA	1-FIREPLACE NOT INSTALLED 2-VENT FAN LEFT SIDE BEDROOM NOT CONNECTED 3-BLOCK SMALL CHASE BETWEEN FRONT TWO BEDROOMS 4-FUR BONUS ROOM TRUSS DOWN FOR R-38 INSULATION 5-AIR BARRIER NEEDED ON WALLS UPSTAIRS AJOINING HEATED AREAS. 6-AIR BARRIER UNDER STAIRS AT GARAGE AREA. OK INSULATE OK TO SIDE
I129 01	4/17/15	TSG	R*INSULATION INSPECTION VRU #: 002647790
	4/17/15	AP	
R425 02	4/17/15	TSG	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002648137
	4/17/15	AP	T/S: 04/16/2015 02:59 PM DJOHNSON -----
H824 01	5/05/15	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002656254
	5/05/15	AP	T/S: 05/06/2015 12:11 PM SSTEWARD ----- T/S: 05/06/2015 12:11 PM SSTEWARD -----
R429 01	5/11/15	TI	FOUR TRADE FINAL VRU #: 002657211

11 AP-IVR

----- COMMENTS AND NOTES -----