

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:** ✓

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SED

Name: Stancil Builders Inc

Address: 32 Yukon Trail

Ferguson Varrio NC 27526

Date: 10-19-15

Building Official: Bear Miller

Permit Numbers

Building: 15-50035524

Electrical: " "

Insulation: " "

Plumbing: " "

Mechanical: " "

MEG Home: _____

ADDRESS : 32 YUKON TRL SUBDIV: HADDEN POINTE II 18LOTS
 CONTRACTOR : STANCIL BUILDERS INC. PHONE : (919) 639-2073
 OWNER : STANCIL BUILDERS & FREDDIE PHONE :
 PARCEL : 08-0652- - -0024- -40-
 APPL NUMBER: 15-50035524 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 02/13/2015 04:04 PM, DJOHNSON --
 HADDEN POINTE PHS 2 LOT 27
 32 YUKON TRL

STRUCTURE: 000 000 48.8X454 3 BR ATT GARAGE DECK CRAWL BSMT
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/29/15	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002652622
	4/29/15	AP	T/S: 04/29/2015 11:34 AM DETAYLOR -----
B103 01	5/15/15	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 002659386
	5/15/15	AP	T/S: May 15, 2015 08:58 AM BSUTTON -----
B105 01	6/15/15	KS	R*OPEN FLOOR VRU #: 002672726
	6/15/15	AP	T/S: 06/15/2015 11:45 AM KSLATTUM -----
A814 01	6/16/15	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002673705
	6/15/15	AP	32 YUKON TRL FUQUAY VARINA 27526
			T/S: 06/15/2015 11:59 AM SBENNETT -----
R425 01	7/13/15	BS	FOUR TRADE ROUGH IN VRU #: 002686472
	7/13/15	DA	T/S: July 13, 2015 02:02 PM BSUTTON ----- Install roof boots on plumbing vents.2. Need a structural nailplate at hall bath vanity vent on one side of top plate. OK TO SIDE. DO NOT INSULATE
R425 02	7/16/15	BS	FOUR TRADE ROUGH IN VRU #: 002688620
	7/16/15	DA	T/S: July 16, 2015 10:37 AM BSUTTON ----- Still need nail plate. Need air barriers at fireplace. Check at insulation
I129 01	7/24/15	BS	R*INSULATION INSPECTION VRU #: 002693482
	7/24/15	AP	T/S: July 24, 2015 10:15 AM BSUTTON -----
R425 03	7/24/15	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002693661
	7/24/15	AP	T/S: 07/23/2015 02:28 PM DJOHNSON ----- T/S: July 24, 2015 10:15 AM BSUTTON -----
H824 01	8/03/15	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002698553
	8/03/15	AP	T/S: 08/04/2015 10:32 AM SSTEWARD ----- T/S: 08/04/2015 10:32 AM SSTEWARD -----
R429 01	10/15/15	BS	FOUR TRADE FINAL VRU #: 002730101
	10/15/15	DA	T/S: October 15, 2015 10:48 AM BSUTTON ----- 1. Change posted address to 32. 2. Complete energy efficiency card. Ok for power
R429 02	10/19/15	TI	FOUR TRADE FINAL VRU #: 002731208

10-19-15 APBS

COMMENTS AND NOTES