

2

COUNTY OF HARNETT DEPARTMENT OF BUILDING INSPECTION AND PLANNING/DEVELOPMENT CERTIFICATE OF OCCUPANCY

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: Residential

Owner: Weaver Development

911 Address: 50. King rock

State: NC Zip Code: _____

Date: 7/29/15

S. C. [Signature]
Building Official

PERMIT NUMBERS

Building Permit No.: _____

Electrical Permit No.: _____

Insulation Permit No.: _____

Plumbing Permit No.: _____

Mech. Permit No.: _____

MFG. Home: _____

754
5003

PREPARED 7/28/15, 14:21:26
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 10
DATE 7/29/15

ADDRESS : 50 RINGNECK CT
CONTRACTOR :
OWNER : WEAVER DEVELOPMENT COMPANY INC
PARCEL : 13-0630- - -0096- -39-
APPL NUMBER: 15-50035754 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 03/23/2015 09:36 AM JBROCK
THOMAS MANOR - OFF OF OLD 421 - LOT 24

SUBDIV: THOMAS MANOR 36LOTS
PHONE :
PHONE :

STRUCTURE: 000 000 38X57 3BDR CRAWL W/ GARAGE
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3000000.00
SEPTIC - EXISTING? : NEW TANK

PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/30/15	TSG	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002652972
A814 01	4/30/15 5/04/15 5/05/15	AP SB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002654762 50 RINGNECK CT LILLINGTON 27546 T/S: 05/05/2015 08:41 AM SBENNETT R*BLDG FOUND & TEMP SVC POLE VRU #: 002654754
B103 01	5/05/15	TSG	
B105 01	5/05/15 6/01/15	AP TSG	R*OPEN FLOOR VRU #: 002666113
R425 01	6/01/15 6/24/15 6/24/15	AP MR DA	FOUR TRADE ROUGH IN VRU #: 002678514 T/S: 06/24/2015 02:33 PM MREARIC repair strap needed at break in tiop plate in garage // close up all air barriers and foam cracks // strap all trusses for uplift // ok to insulate
I129 01	6/25/15	TSG	R*INSULATION INSPECTION VRU #: 002678944 Afternoon inspection if possible. Please
H824 01	6/25/15 7/15/15 7/15/15	AP OT AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002689008 T/S: 07/16/2015 08:47 AM SSTEWARD T/S: 07/16/2015 08:47 AM SSTEWARD
R429 01	7/28/15 7/28/15	TSG DA	FOUR TRADE FINAL VRU #: 002694248 1- child locks second floor 2- pinched duct in crawl under master 3- water heater requires air gap at prv pipe
R429 02	7/29/15	TI	FOUR TRADE FINAL VRU #: 002695187

[Handwritten signatures]

COMMENTS AND NOTES