## COUNTY OF HARNETT DEPARTMENT OF BUILDING INSPECTION AND PLANNING/DEVELOPMENT CERTIFICATE OF OCCUPANCY

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use, For the following:

Use Classification:	PERMIT NUMBERS
Owner: Welver Development	Building Permit No.:
911 Address: 28/Widgeon Way	Electrical Permit No.:
	Insulation Permit No.:
	Plumbing Permit No.:
State: _/UC Zip Code:	Mech. Permit No.:
Date: 9/18/18	MFG. Home:
) (ruy	
Building Official	

71976084

PREPARED 9/17/15, 14:16:27 Harnett County INSPECTION TICKET
INSPECTOR: IVR

PAGE

DATE 9/18/15

33

ADDRESS . : 281 WIDGEON WAY SUBDIV: THOMAS MANOR 36LOTS

CONTRACTOR : WEAVER DEVELOPMENT CO INC PHONE : (910) 433-0888

OWNER . . : WEAVER DEVELOPMENT COMPANY INC PHONE :

PARCEL . . : 13-0630- - -0096- -18-

APPL NUMBER: 15-50036604 CP NEW RESIDENTIAL (SFD)
DIRECTIONS: T/S: 07/08/2015 03:05 PM LBENNETT -OLD US 421 NORTH, AFTER PASSING NEIL
THOMAS ROAD THOMAS MANOR IS ON LEFT

SIDE. LOT 13 IS ON THE RIGHT AT THE END

OF THE PROJECT

STRUCTURE: 000 000 56X59 SFD 3BDR W/GARAGE SLAB

FLOOD ZONE . . . : FLOOD ZONE X

# BEDROOMS . . . . : 3.00 PROPOSED USE . . . . : SFD SEPTIC - EXISTING? . . . : NEW WATER SUPPLY . . . . : COUNTY

PERMIT: CPSF 00 CP * SFD  REQUESTED INSP DESCRIPTION			
TYP/SQ	COMPLETED		RESULTS/COMMENTS
B101 01	7/24/15	TSG	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002693133
	7/23/15	AP	
B103 01	, ,	TSG	R*BLDG FOUND & TEMP SVC POLE VRU #: 002695203
	7/29/15	AP	·
A814 01		SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002695211
	7/29/15	AP	281 WIDGEON WAY LILLINGTON 27546
			T/S: 07/29/2015 09:33 AM SBENNETT
P309 01	8/03/15	TSG	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002697746
	8/03/15	AP	
B111 01	8/04/15	TSG	R*BLDG SLAB INSP/TEMP SVC POLE VRU #: 002697886
	8/04/15	AP	
R425 01		TSG	FOUR TRADE ROUGH IN VRU #: 002706596
	8/24/15	DA	1- anchor bolts missing on front wall at main entry,
			2-check dryer duct length. 35 max 3-fill concrete around
			drains under tubs and shower
I129 01	8/25/15	TSG	R*INSULATION INSPECTION VRU #: 002706638
	8/25/15	AP	
R425 02	8/25/15	TSG	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002708048
	8/25/15	AP	T/S: 08/24/2015 02:21 PM DJOHNSON
H824 01	9/03/15	BM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002714301
	9/03/15	AP	T/S: 09/04/2015 11:47 AM SSTEWART
	/	- 0	T/S: 09/04/2015 11:47 AM SSTEWART
R429 01	0/1/1/15	TA	FOUR TRADE FINAL VRU #: 002720019
	$-\chi$		

----- COMMENTS AND NOTES -----