Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Applicant:

Owner:

Address:

Description

System Type(s) Site LTAR

Available Space (.1945)

Initial

System

Repair System

Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Date Evaluated:

Location Water Evalua	ss: sed Facility: on of Site: Supply: tion Method f Wastewate	:D Auge	Desig Prope	rty Recorded:  In Flow (.1949): 148  Inty Recorded:  Individual Wall Wall Wall Wall Wall Wall Wall W	Vell Spring	Oth	er			
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS					
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
1	1.5 2.5	0-8	GSL	NES US /US						
		8-36	58×5(1	verrolap Fa solik	4				P5 -35	
2		0-6	() 52	vac ishq For sot						
		6-38	SBREL	FR salsp						
				Tal.						
										-

Other Factors (.1946):

Site Classification (.1948):

Evaluated By: 81

Others Present:

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET	
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY	
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM	SS-SLIGHTY STICKY S-STICKY VS-VERY STICKY	
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	EFI-EXTREMELY FIRM	NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC	

ΙV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

SG-SINGLE GRAIN M- MASSIVE

MINERALOGY SLIGHTLY EXPANSIVE

**EXPANSIVE** 

CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

PR-PRISMATIC

Show profile locations and other site features (dimensions, references or benchmark, and North)

