Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Applicant:

Description

Available Space (.1945) System Type(s) Site LTAR

Initial

System

Repair System

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Locati Water Evalua	ss: sed Facility: on of Site: Supply:	d:□ Auge	Applicant: Date Evaluated: Design Flow (.1949): Property Size: Property Recorded: Public Individual Well Spring Other Auger Boring Pit Cut Sewage Industrial Process Mixed						
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,4	L-30%	0-16	SL.						
		20-44	Suciay		35-36-7.181				,
2.3	L-	U- 24	wei stion						
		24-40	st-lon-	<i>y</i> —	20:24				V
									,
									9
				v					
					â				

Other Factors (.1946): Site Classification (.1948):

Evaluated By: Others Present: