

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential
Name: Stancil Builders Inc

Permit Numbers

Building: _____
Electrical: _____
Insulation: _____
Plumbing: _____
Mechanical: 15-50037169
MFG Home: _____

Address: 240 Oxfordshire Dr
Fuquay-Varina, NC 27526

Date: 6-29-16

Building Official: [Signature]

 ADDRESS . . : 240 OXFORDSHIRE DR
 CONTRACTOR : STANCIL BUILDERS INC.
 OWNER . . . : STANCIL BUILDERS INC
 PARCEL . . . : 08-0652- - -0024- -29-
 APPL NUMBER: 15-50037169 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 09/23/2015 03:49 PM JBROCK ----
 HADDEN POINTE #15R

SUBDIV: HADDEN POINTE II 18LOTS
 PHONE : (919) 639-2073
 PHONE :

76160267

STRUCTURE: 000 000 52X39 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3000000.00
 SEPTIC - EXISTING? : NEW TANK

PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/02/16	BS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002783504
	3/02/16	AP	T/S: 03/01/2016 01:57 PM LBENNETT ----- T/S: March 02, 2016 09:59 AM BSUTTON -----
A814 01	3/11/16	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002787778
	3/11/16	AP	240 Oxfordshire Dr Fuquay Varina 27526 Lot 15R T/S: 03/11/2016 09:18 AM TWARD -----
B103 01	3/11/16	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002787760
	3/11/16	AE	T/S: March 11, 2016 08:33 AM BSUTTON ----- Check damproofing at open floor
B103 02	3/28/16	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002794816
	3/28/16	AP	T/S: 03/24/2016 02:16 PM JFORBES ----- T/S: March 28, 2016 11:03 AM BSUTTON -----
B105 01	3/28/16	BS	R*OPEN FLOOR TIME: 17:00 VRU #: 002794824
	3/28/16	AP	T/S: 03/24/2016 02:18 PM JFORBES ----- T/S: March 28, 2016 11:03 AM BSUTTON -----
R425 01	4/12/16	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002801959
	4/12/16	DA	T/S: 04/11/2016 02:08 PM JFORBES ----- T/S: April 12, 2016 11:08 AM BSUTTON ----- Need electrical nailplates at kitchen wall at rear porch beam jack studs. Ok to side/insulate
I129 01	4/14/16	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002803013
	4/14/16	AP	-----
R425 02	4/14/16	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002803021
	4/14/16	AP	5/S: 04/13/2016 02:16 PM JBROCK -----
H824 01	6/01/16	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002828408
	6/01/16	AP	T/S: 06/08/2016 04:20 PM SSTEWARD ----- T/S: 06/08/2016 04:21 PM SSTEWARD -----
R429 01	6/24/16	BS	FOUR TRADE FINAL TIME: 17:00 VRU #: 002835825
	6/24/16	DA	T/S: 06/23/2016 12:47 PM LBENNETT ----- T/S: June 24, 2016 10:01 AM BSUTTON ----- 1.No makeup air for washer/dryer closet. 2. Could not verify depth of insulation in attic. 3. Insulation missing in floor system around HVAC return.
R429 02	6/29/16	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002836765
	6/29/16	AP	T/S: 06/27/2016 10:11 AM LBENNETT ----- T/S: 06/27/2016 01:46 PM JFORBES -----

 COMMENTS AND NOTES
