

**COUNTY OF HARNETT**  
**Building Inspections Department**  
**Planning Services**

**Certificate of Compliance:** \_\_\_\_\_ **Occupancy:** ✓

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Name: W&H Onsite Homes LLC

Address: 221 Winged Foot Dr

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Date: 12-14-16

Building Official: James Hall

**Permit Numbers**

Building: \_\_\_\_\_

Electrical: 15-50037639

Insulation: \_\_\_\_\_

Plumbing: \_\_\_\_\_

Mechanical: \_\_\_\_\_

MFG Home: \_\_\_\_\_

-----

ADDRESS : 221 WINGED FOOT DR SUBDIV: WALNUT GROVE 37LOTS  
 CONTRACTOR : H & H ONSITE HOMES LLC PHONE : (910) 486-4864  
 OWNER : EVEN PAR DEVELOPMENT LLC PHONE :  
 PARCEL : 01-0525- - -0062- -13-  
 APPL NUMBER: 15-50037639 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 12/03/2015 01:36 PM JBROCK ----  
 221 WINGED FOOT DR LOT 4

-----

**STRUCTURE: 000 000 35X42 4BDR CRAWL W/ GARAGE**

FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 4000000.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

-----

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/09/16 6/09/16	JH AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002828127 T/S: 06/08/2016 01:17 PM JBROCK -----
A814 01	7/06/16 7/06/16	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002839876 221 WINGED FOOT DR BUNNLEVEL 28323 T/S: 07/06/2016 11:16 AM TWARD -----
B103 01	7/06/16 7/06/16	JH DA	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002839850 T/S: 07/05/2016 02:15 PM JBROCK ----- 1)Remove water and dirt from top of footing inside & outside of foundation wall.2)Need drain pipe for foundation wall so it will drain per code. T-POLE PASSED
B103 02	7/20/16 7/20/16	JH AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002845782 T/S: 07/18/2016 04:02 PM JFORBES -----
E207 01	7/25/16 7/25/16	JH AP	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 002848208 T/S: 07/22/2016 03:53 PM DJOHNSON ----- T-POLE WAS PASSED on 7/6/16 -----
B105 01	7/28/16 7/28/16	JH AP	R*OPEN FLOOR TIME: 17:00 VRU #: 002849750 T/S: 07/27/2016 10:36 AM LBENNETT -----
B111 01	8/26/16 8/26/16	MR AP	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002862142 T/S: 08/24/2016 03:03 PM JBROCK ----- slab for the porchs & garage T/S: 08/26/2016 02:17 PM MREARIC -----
R425 01	8/31/16 8/31/16	JH CA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002864791 T/S: 08/30/2016 02:10 PM JBROCK ----- NOT READY -----
R425 02	9/09/16 9/09/16	MR DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002868594 T/S: 09/08/2016 11:05 AM JBROCK ----- T/S: 09/09/2016 02:28 PM MREARIC ----- fireblock wall at washer fix plumbing and dryer vent wires frayed at hall box just outside of master br install air barriers everywhere per code air barrier needed behind tub install barriers at 2nd Fl. perimeter no water in riser provide a hanger per specs at junction of double truss D-01

ADDRESS : 221 WINGED FOOT DR SUBDIV: WALNUT GROVE 37LOTS  
 CONTRACTOR : H & H ONSITE HOMES LLC PHONE : (910) 486-4864  
 OWNER : EVEN PAR DEVELOPMENT LLC PHONE :  
 PARCEL : 01-0525- - -0062- -13-  
 APPL NUMBER: 15-50037639 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			and other double 1800# support secure all wiring per code install truss clips at C-03 trusses good luck jimmy
R425 03	9/15/16 9/15/16	JH CA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002871929 T/S: 09/14/2016 02:04 PM JBROCK ----- PER CARTER -----
R425 04	9/16/16 9/16/16	MR DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002872539 T/S: 09/15/2016 01:45 PM JBROCK ----- T/S: 09/16/2016 12:57 PM MREARIC ----- OK to insulate , but you still need air barriers under master tub at garage wall and behind the shower on 2nd floor at attic side.
I129 01	9/20/16 9/20/16	JH AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002873685 T/S: 09/19/2016 02:02 PM LBENNETT -----
R425 05	9/20/16 9/20/16	JH AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002873669 T/S: 09/19/2016 02:02 PM LBENNETT -----
H824 01	11/14/16 11/14/16	OT AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002900991 T/S: 11/18/2016 01:19 PM KHINSON ----- T/S: 11/18/2016 01:19 PM KHINSON -----
E209 01	11/18/16 11/18/16	JH DA	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002899813 T/S: 11/16/2016 04:02 PM JBROCK ----- 1)Water heater not wired.2)Exposed wires behind refrigerator,under sink & to right of sink.3)No light in half bath.4)Missing light switch in back right bedroom closet.5)Missing receptacle behind doors in front right bedroom & left bedroom.6)Loose wires under house at crawl door.
M305 01	11/18/16 11/18/16	JH AP	R*PLUMB SEWER CONNECTION TIME: 17:00 VRU #: 002899821 T/S: 11/16/2016 04:02 PM JBROCK ----- T/S: 11/16/2016 04:02 PM JBROCK -----
P307 01	11/18/16 11/18/16	JH AP	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 002899847 T/S: 11/16/2016 04:02 PM JBROCK -----
E209 02	11/23/16 11/23/16	MR AP	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002901932 T/S: 11/21/2016 03:45 PM JBROCK ----- T/S: 11/23/2016 01:34 PM MREARIC -----
R429 01	12/12/16 12/12/16	JH DA	FOUR TRADE FINAL TIME: 17:00 VRU #: 002908739 T/S: 12/09/2016 08:44 AM JBROCK ----- 1)Sewer pump alarm not working.2)Missing sheetrock on exterior wall to right of refrigerator.3)Missing weatherstripping & attach insulation to attic access door.4) Need 4" below crawl door opening.
R429 02	12/14/16	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002910198

ADDRESS : 221 WINGED FOOT DR  
CONTRACTOR : H & H ONSITE HOMES LLC  
OWNER : EVEN PAR DEVELOPMENT LLC  
PARCEL : 01-0525- - -0062- -13-  
APPL NUMBER: 15-50037639 CP NEW RESIDENTIAL (SFD)

SUBDIV: WALNUT GROVE 37LOTS  
PHONE : (910) 486-4864  
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
--------	------------------------	----------------	---------------------------------

12-14-16 APTY

T/S: 12/13/2016 09:10 AM JBROCK

COMMENTS AND NOTES