

**COUNTY OF HARNETT  
Building Inspections Department  
Planning Services**

**Certificate of Compliance:** \_\_\_\_\_ **Occupancy:**   X  

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification:   SFD  

Name:   Keith Michael Brown  

Address:   35 Buckhorn Farms Lane  

  Holly Springs NC 27540  

**Date:**   05/16/2016  

**Permit Numbers**

Building:   16-50037856  

Electrical:   XXXXXXXXXXXXXXXXXXXXXXXX  

Insulation:   XXXXXXXXXXXXXXXXXXXXXXXX  

Plumbing:   XXXXXXXXXXXXXXXXXXXXXXXX  

Mechanical:   XXXXXXXXXXXXXXXXXXXXXXXX  

~~MPG~~   XXXXXXXXXXXXXXXXXXXXXXXX  

**Building Official:**   Brad Sutton

ADDRESS : 35 BUCKHORN FARMS LN  
CONTRACTOR : BROWN KEITH MICHAEL  
OWNER : BUCKHORN FARMS  
PARCEL : 05-0625- - -0021- -04-  
APPL NUMBER: 16-50037856 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : T/S: 01/15/2016 10:40 AM JBROCK ----  
BUCKHORN FARMS #2  
PREMISE # 62794035

SUBDIV: ROGER M CALLIS  
PHONE : (919) 772-2166  
PHONE :

STRUCTURE: 000 000 52X55 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X  
# BEDROOMS : 3000000.00 PROPOSED USE : SFD  
SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/10/16	BS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002775278
	2/10/16	AP	T/S: February 10, 2016 09:08 AM BSUTTON -----
A814 01	2/23/16	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002779932
	2/23/16	AP	35 BUCKHORN FARMS LN HOLLY SPRINGS 27540 T/S: 02/23/2016 09:07 AM SBENNETT -----
B103 01	2/23/16	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002779924
	2/23/16	DA	T/S: 02/22/2016 02:14 PM LBENNETT ----- T/S: 02/23/2016 01:30 PM MREARIC ----- install a foundation drain hole. OK to continue detached garage not included in this inspection
B103 02	3/02/16	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002783207
	3/02/16	AP	T/S: March 02, 2016 12:14 PM BSUTTON -----
B105 01	3/04/16	BS	R*OPEN FLOOR TIME: 17:00 VRU #: 002785012
	3/04/16	AP	T/S: March 04, 2016 03:24 PM BSUTTON -----
R425 01	3/22/16	KS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002792414
	3/22/16	DA	T/S: 03/22/2016 03:46 PM KSLATTUM ----- Need repair for 3 broken trusses in garage.
I129 01	3/29/16	KS	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002794998
	3/29/16	AP	T/S: 03/29/2016 02:52 PM KSLATTUM -----
R425 02	3/29/16	KS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002795003
	3/29/16	AP	T/S: 03/29/2016 02:52 PM KSLATTUM -----
M305 01	4/21/16	BS	R*PLUMB SEWER CONNECTION TIME: 17:00 VRU #: 002805836
	4/21/16	AP	T/S: 04/20/2016 01:23 PM LBENNETT ----- T/S: April 21, 2016 10:01 AM BSUTTON -----
R125 01	4/21/16	BS	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002805828
	4/21/16	AP	T/S: 04/20/2016 01:22 PM LBENNETT ----- STONE VENEER T/S: April 21, 2016 10:01 AM BSUTTON -----
E209 01	5/11/16	MR	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002815629
	5/11/16	AP	T/S: 05/11/2016 01:17 PM JBROCK ----- T/S: 05/11/2016 02:51 PM MREARIC ----- premise# 62794035 garage feeder is not to code ; the neutral and ground are paralleled and there is no main disconnect on the garage
H824 01	5/12/16	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002816494
	5/12/16	AP	T/S: 05/13/2016 11:57 AM SSTEWARD ----- T/S: 05/13/2016 11:57 AM SSTEWARD -----