

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Name: Michael Keith Brown

Address: 119 Buckhorn Farms

Holly Springs NC 27540

Date: 05/06/2016

Permit Numbers

Building: 16-50037857

Electrical:

Insulation:

Plumbing:

Mechanical:

~~MPC00000XXXXXXXXXXXXXXXXXXXX~~

Building Official: Brad Sutton

ADDRESS : 119 BUCKHORN FARMS LN SUBDIV: T W TRUELOVE ESTATE
CONTRACTOR : BROWN KEITH MICHAEL PHONE : (919) 772-2166
OWNER : BUCKHORN FARMS PHONE :
PARCEL : 05-0625- - -0021- -06-
APPL NUMBER: 16-50037857 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 01/15/2016 10:40 AM JBROCK ----
BUCKHORN FARMS #4

STRUCTURE: 000 000 52X55 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3000000.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/10/16	BS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002775260
	2/10/16	AP	T/S: February 10, 2016 09:08 AM BSUTTON -----
B103 01	2/19/16	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 002778520
	2/19/16	AP	T/S: February 19, 2016 09:56 AM BSUTTON ----- Foundation is ok. Tpole is missing front cover.
A814 01	2/19/16	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002778512
	2/19/16	AP	119 BUCKHORN FARMS LN HOLLY SPRINGS 27540 T/S: 02/19/2016 09:00 AM TWARD -----
B105 01	3/02/16	BS	R*OPEN FLOOR TIME: 17:00 VRU #: 002783181
	3/02/16	AP	T/S: March 02, 2016 12:14 PM BSUTTON -----
R425 01	3/16/16	BS	FOUR TRADE ROUGH IN VRU #: 002789790
	3/16/16	DA	T/S: March 16, 2016 10:07 AM BSUTTON ----- A05 Needs braces. 2. Midstory guide on Master lav vent. 3. Air barriers on either side of stairway. 4. Install window at master bath. OK to side /insulate
I129 01	3/18/16	BS	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002791184
	3/18/16	AP	T/S: March 18, 2016 10:39 AM BSUTTON -----
R425 02	3/18/16	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002791192
	3/18/16	AP	T/S: March 18, 2016 10:39 AM BSUTTON -----
R125 01	3/29/16	KS	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002795763
	3/29/16	AP	stone inspection T/S: 03/29/2016 02:52 PM KSLATTUM -----
H824 01	4/08/16	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002801702
	4/08/16	AP	T/S: 04/11/2016 10:19 AM SSTEWARD ----- T/S: 04/11/2016 10:19 AM SSTEWARD -----
M305 01	4/21/16	BS	R*PLUMB SEWER CONNECTION TIME: 17:00 VRU #: 002805844
	4/21/16	AP	T/S: 04/20/2016 01:24 PM LBENNETT ----- T/S: April 21, 2016 10:01 AM BSUTTON -----
E209 01	5/02/16	MR	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002809754
	5/02/16	AP	T/S: 04/28/2016 02:53 PM JBROCK ----- T/S: 05/02/2016 01:51 PM MREARIC -----
R429 01	5/06/16	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002812980
	5-6-16	APBS	T/S: 05/05/2016 02:10 PM JFORBES -----

COMMENTS AND NOTES