

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: RESIDENTIAL

Name: HUBERT & RUTH SULLIVAN

Address: 218 SARDINE TRL

Date: 3/26/18

Building Official: [Signature]

Permit Numbers

Building: 16-50038064

Electrical: 11

Insulation: 11

Plumbing: 11

Mechanical: 11

MFG Home: _____

ADDRESS : 218 SAPONI TRL SUBDIV:
 CONTRACTOR : PHONE :
 OWNER : SULLIVAN HUBERT & RUTH S PHONE :
 PARCEL : 05-0633- - -0112- -06-
 APPL NUMBER: 16-50038064 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 02/24/2016 11:23 AM LBENNETT --
 401 TURN LEFT ONTO CHRISTIAN LIGHT RD -
 THEN LEFT ONTO COKESBURY - THEN LEFT ON
 CEDAR ROCK TRAIL - RIGHT ON SAPONI
 T/S: 03/08/2016 08:18 AM DJOHNSON --
 *****PREMISE NO 23711930*****

STRUCTURE: 000 000 80X32 SFD 3BDR BASEMENT

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

| TYP/SQ | REQUESTED COMPLETED | INSP RESULT | DESCRIPTION RESULTS/COMMENTS |
|---------|----------------------|-------------|--|
| B101 01 | 4/05/16 4/05/16 | BS DA | R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002798585 T/S: 04/04/2016 11:11 AM JFORBES ----- T/S: April 05, 2016 09:55 AM BSUTTON ----- Need GFCI at tpole. Tie and support rebar in footing. Footing to be backfilled (Basement) |
| B101 02 | 4/06/16 4/06/16 | BS AP | R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002799138 T/S: 04/05/2016 10:17 AM DJOHNSON ----- TSP INSPECTION ALSO T/S: April 06, 2016 09:43 AM BSUTTON ----- Partial. Will check interior basement piers at foundation inspection |
| A814 01 | 5/03/16 5/03/16 | SB AP | ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002810828 218 SAPONI TRL FUQUAY VARINA 27526 T/S: 05/03/2016 09:12 AM SBENNETT ----- |
| B103 01 | 5/03/16 5/03/16 | KS AP | R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002810810 T/S: April 06, 2016 09:43 AM BSUTTON ----- Partial. Will check interior basement piers at foundation inspection T/S: 05/03/2016 03:11 PM KSLATTUM ----- |
| B105 01 | 6/07/16 6/07/16 | BS AP | R*OPEN FLOOR VRU #: 002826337 T/S: June 07, 2016 11:38 AM BSUTTON ----- |
| R125 01 | 9/15/16 9/15/16 | BS AP | ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002871648 T/S: 09/14/2016 09:36 AM LBENNETT ----- SHEATHING INSPECTION T/S: September 15, 2016 08:21 AM BSUTTON ----- Block and nail all joints in OSB at corners and every 25 feet in the basement and on the first floor. Will check at framing inspection. OK to side |
| R425 01 | 12/16/16 12/16/16 | BS CA | FOUR TRADE ROUGH IN VRU #: 002911549 T/S: December 16, 2016 11:57 AM BSUTTON ----- |
| R425 02 | 7/11/17 7/11/17 | BS DA | FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002995009 T/S: 07/10/2017 10:53 AM LLUCAS ----- T/S: July 11, 2017 01:28 PM BSUTTON ----- Remove all #14 from 20 amp circuits. 2. Need water on master shower. 3. Truss bracing at hip trusses each end . |

ADDRESS : 218 SAPONI TRL SUBDIV:
 CONTRACTOR : PHONE :
 OWNER : SULLIVAN HUBERT & RUTH S PHONE :
 PARCEL : 05-0633- - -0112- -06-
 APPL NUMBER: 16-50038064 CP NEW RESIDENTIAL (SFD)

| TYP/SQ | REQUESTED COMPLETED | INSP RESULT | DESCRIPTION RESULTS/COMMENTS |
|---------|----------------------|-----------------|--|
| | | | 4. Firestop all holes top and bottom plates. 4. Bath receptacles must be on a dedicated 20 amp circuit. 5. Need a mistory guide at kitchen vent. |
| R425 03 | 7/13/17 7/13/17 | DT DA | FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002996411 T/S: 07/12/2017 11:14 AM LLUCAS ----- T/S: 07/13/2017 03:07 PM DETAYLOR ----- Still some holes for interior walls missing fire caulk Okay to insulate |
| I129 01 | 7/20/17 7/20/17 | BS DA | R*INSULATION INSPECTION TIME: 17:00 VRU #: 003000197 T/S: 07/19/2017 12:58 PM JBROCK ----- T/S: July 20, 2017 11:31 AM BSUTTON ----- Close top of chase created by framing at end of hallway HVAC return. Use 3/4 ply min. or 2x material and firecaulk all gaps. 2. Windows must be caulked or foamed. Ok to hang sheetrock. Do not cover windows or chase |
| R425 04 | 7/20/17 7/20/17 | BS DA | FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003000213 T/S: 07/19/2017 12:58 PM JBROCK ----- T/S: July 20, 2017 11:31 AM BSUTTON ----- Close top of chase created by framing at end of hallway HVAC return. Use 3/4 ply min. or 2x material and firecaulk all gaps. 2. Windows must be caulked or foamed. Ok to hang sheetrock. Do not cover windows or chase |
| I129 02 | 7/25/17 7/25/17 | BS AP | R*INSULATION INSPECTION TIME: 17:00 VRU #: 003002169 T/S: 07/24/2017 08:42 AM LLUCAS ----- T/S: July 25, 2017 11:08 AM BSUTTON ----- |
| R425 05 | 7/25/17 7/25/17 | BS AP | FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003002177 T/S: 07/24/2017 08:42 AM LLUCAS ----- T/S: July 25, 2017 11:08 AM BSUTTON ----- |
| E209 01 | 11/14/17 11/14/17 | BS AP | R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 003052115 T/S: 11/13/2017 08:09 AM LLUCAS ----- T/S: November 14, 2017 11:41 AM BSUTTON ----- |
| H824 01 | 12/05/17 12/05/17 | JM AP | ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 003063120 T/S: 12/06/2017 10:32 AM KHINSON ----- T/S: 12/06/2017 10:34 AM KHINSON ----- |
| R429 01 | 3/21/18 3/21/18 | MC DA | FOUR TRADE FINAL TIME: 17:00 VRU #: 003103827 T/S: 03/20/2018 10:43 AM BPETRICH ----- T/S: 03/21/2018 03:22 PM MCOOK ----- |
| | | | 1. install thermal expansion tank 2. install co det 3. install 2 rec. in island 4. install weather strip around door to basement storage area |
| R429 02 | 3/26/18 <u>11</u> | TI <u>AP</u> | FOUR TRADE FINAL TIME: 17:00 VRU #: 003105905 T/S: 03/23/2018 02:06 PM LLUCAS ----- |

COMMENTS AND NOTES

ADDRESS : 218 SAPONI TRL SUBDIV:
 CONTRACTOR : PHONE :
 OWNER : SULLIVAN HUBERT & RUTH S PHONE :
 PARCEL : 05-0633- - -0112- -06-
 APPL NUMBER: 16-50038064 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 02/24/2016 11:23 AM LBENNETT --
 401 TURN LEFT ONTO CHRISTIAN LIGHT RD -
 THEN LEFT ONTO COKESBURY - THEN LEFT ON
 CEDAR ROCK TRAIL - RIGHT ON SAPONI
 T/S: 03/08/2016 08:18 AM DJOHNSON --
 *****PREMISE NO 23711930*****

STRUCTURE: 000 000 80X32 SFD 3BDR BASEMENT

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

| TYP/SQ | REQUESTED COMPLETED | INSP RESULT | DESCRIPTION RESULTS/COMMENTS |
|---------|---------------------------|-------------------|--|
| B101 01 | 4/05/16 4/05/16 | BS DA | R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002798585 T/S: 04/04/2016 11:11 AM JFORBES ----- T/S: April 05, 2016 09:55 AM BSUTTON ----- Need GFCI at tpole. Tie and support rebar in footing. Footing to be backfilled (Basement) |
| B101 02 | 4/06/16 4/06/16 | BS AP | R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002799138 T/S: 04/05/2016 10:17 AM DJOHNSON ----- TSP INSPECTION ALSO T/S: April 06, 2016 09:43 AM BSUTTON ----- Partial. Will check interior basement piers at foundation inspection |
| A814 01 | 5/03/16 5/03/16 | SB AP | ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002810828 218 SAPONI TRL FUQUAY VARINA 27526 T/S: 05/03/2016 09:12 AM SBENNETT ----- |
| B103 01 | 5/03/16 5/03/16 | KS AP | R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002810810 T/S: April 06, 2016 09:43 AM BSUTTON ----- Partial. Will check interior basement piers at foundation inspection T/S: 05/03/2016 03:11 PM KSLATTUM ----- |
| B105 01 | 6/07/16 6/07/16 | BS AP | R*OPEN FLOOR VRU #: 002826337 T/S: June 07, 2016 11:38 AM BSUTTON ----- |
| R125 01 | 9/15/16 <u>9.15.16</u> | TI <u>APBS</u> | ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002871648 T/S: 09/14/2016 09:36 AM LBENNETT ----- SHEATHING INSPECTION |

COMMENTS AND NOTES