

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Shean Michael D.

Address: 333 Antioch Church Rd
Dunn, NC 28334

Date: 11/23/16

Building Official: _____

Permit Numbers

Building: _____

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: 16-50038392

MFG Home: _____

[Signature]

ADDRESS : 333 ANTIOCH CHURCH RD
 CONTRACTOR :
 OWNER : SHEAN MICHAEL D
 PARCEL : 06-1506- - -0064- -01-
 APPL NUMBER: 16-50038392 CP NEW RESIDENTIAL (SFD)

SUBDIV:
 PHONE :
 PHONE :

DIRECTIONS : T/S: 04/04/2016 03:20 PM JBROCK ----
 421 S TO ERWIN R ON N 13TH ST THEN L ON
 IRIS BRYANT RD SPLIT GO STRAIGHT IS
 ANTIOCH CHURCH RD ON LEFT

*Jimmy called
 and the septic
 is ok.*

STRUCTURE: 000 000 55X61 3BDR SLAB W/ GARAGE BR STORAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3000000.00
 SEPTIC - EXISTING? : NEW TANK
 PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	8/23/16 8/23/16	DT DA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002860740 T/S: 08/22/2016 12:08 PM LBENNETT ----- T/S: 08/23/2016 01:16 PM DETAYLOR ----- Footing dug does not match approved plans
B101 02	8/24/16 8/24/16	DT AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002861367 T/S: 08/23/2016 01:24 PM JBROCK ----- T/S: 08/24/2016 03:02 PM DETAYLOR -----
B101 03	8/26/16 8/26/16	DT AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002862555 DEEN SEE KEN T/S: 08/26/2016 01:01 PM DETAYLOR -----
A814 01	8/29/16 8/29/16	SB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002862936 333 ANTIOCH CHURCH RD DUNN 28334 T/S: 08/29/2016 04:05 PM SBENNETT -----
B103 01	8/29/16 8/29/16	DT AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002862928 T/S: 08/26/2016 11:48 AM JBROCK ----- T/S: 08/29/2016 11:29 AM DETAYLOR -----
P309 01	9/08/16 9/08/16	DT AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002867976 T/S: 09/07/2016 11:52 AM JBROCK ----- T/S: 09/08/2016 04:34 PM DETAYLOR -----
B111 01	9/13/16 9/13/16	DT AP	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002869295 T/S: 09/12/2016 09:04 AM JBROCK ----- T/S: 09/13/2016 12:26 PM DETAYLOR -----
R425 01	10/13/16 10/13/16	KS DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002883841 T/S: 10/12/2016 11:33 AM JBROCK ----- T/S: 10/13/2016 03:16 PM KSLATTUM ----- 1. A01 and A03 missing bracing 2. Uplift missing on A04 3. fire block betwee wall and ceiling intersection at master bathroom and closet 4. A05 web bracing 5. B2 not braced. Trusses not completed. Someone other than me needs to read them and install accordingly. 6. Repair air barriers. 7 Need bonus room baffles. Talk to me about the stairs.
I129 01	10/17/16 10/17/16	DT DA	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002885390 T/S: 10/14/2016 12:45 PM DJOHNSON ----- T/S: 10/17/2016 03:28 PM DETAYLOR -----

ADDRESS : 333 ANTIOCH CHURCH RD SUBDIV:
 CONTRACTOR : PHONE :
 OWNER : SHEAN MICHAEL D PHONE :
 PARCEL : 06-1506- - -0064- -01-
 APPL NUMBER: 16-50038392 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R425 02	10/17/16 10/17/16	DT DA	Trusses still not strapped for uplift or web braced in accordance with documents FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002885382 T/S: 10/14/2016 12:45 PM DJOHNSON ----- BONUS ROOM IS CLEAN STORAGE ONLY T/S: 10/17/2016 03:28 PM DETAYLOR ----- Trusses still not strapped for uplift or web braced in accordance with documents
I129 02	10/18/16 10/18/16	DT CA	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002886018 T/S: 10/17/2016 01:43 PM JBROCK ----- T/S: 10/18/2016 12:25 PM DETAYLOR -----
R425 03	10/18/16 10/18/16	DT CA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002886026 * OVERRIDE TAKEN BY JBROCK DATE: 10/17/16 TIME: 13:43:41 T/S: 10/17/2016 01:43 PM JBROCK ----- T/S: 10/18/2016 12:25 PM DETAYLOR -----
I129 03	10/19/16 10/19/16	DT AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002886729 T/S: 10/18/2016 01:26 PM JBROCK ----- T/S: 10/19/2016 01:15 PM DETAYLOR -----
R425 04	10/19/16 10/19/16	DT AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002886711 T/S: 10/18/2016 01:26 PM JBROCK ----- T/S: 10/19/2016 01:15 PM DETAYLOR -----
E209 01	11/15/16 11/21/16	DT AP	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002897973 T/S: 11/14/2016 10:20 AM JBROCK ----- T/S: 11/21/2016 03:25 PM DETAYLOR -----
E209 02	11/16/16 11/16/16	DT AP	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002899029 T/S: 11/15/2016 01:35 PM JBROCK ----- T/S: 11/16/2016 12:07 PM DETAYLOR -----
R429 01	11/23/16 <u>11/23/16</u>	TI <u>AP DT</u>	FOUR TRADE FINAL TIME: 17:00 VRU #: 002902245 T/S: 11/22/2016 10:37 AM JBROCK -----

----- COMMENTS AND NOTES -----