Plan Box # N	1111	Date Job Nai	10/	$\frac{1}{\mu}$
App #	1007	Valuation 18966		et <u>27</u>
				ge <u>5</u>
Inspections for	SFD/SFA			- 329
Crawl	Slab	Mono	Basement	
Footing	Footing	Plum Under Slab	Footing	
Foundation	Foundation	Ele. Under Slab	Foundation -	
Address	Address	Address	Waterproofing	
Open Floor	Slab	Mono Slab	Plum Under slab	
Rough in	Rough In	Rough In	Address	
Insulation	Insulation	Insulation	Slab	
Final	Final	Final	Open Floor	
			Rough In	
			Insulation	
		· · · · · · · · · · · · · · · · · · ·	Final	
Foundation Surve	y En	vir. Health $\underline{\mathcal{NEN}}$	Other	
				-
4.1.11.1	•••••	• • • • • • • • • • • • • • • • • • • •		
Additions / Other		·		
- .•				
Footing				
Foundation				
5lab				
Mono				
Open Floor				
lough In				
7				
nsulation				
inal				