Department of Environment, Health and Natura	
Division of Environmental Health	
On-Site Wastewater Section	

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Address: Proposed Facility: Location of Site: Water Supply: Evaluation Method Type of Wastewate	Publ	ed: Well	Property Size: Spring Mixed	☐ Other	19
P R					

sources

L Lar	.1940	20	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
١	2.5% CV/L	0-35	CLS	VFR ~5/mp					
		35-48	Sgr Scz	VFR ~3/mp For ss/sp				-	P5
				•					
2		0.31	C LS	ver ushe					
2		39-4	Sg X SCL	VEN USING					P3
									1 1 1 1 1 1
									•
									s
					,				

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948): ?
Available Space (.1945)		,	Evaluated By:
System Type(s)	brm	P 25-6/0	Others Present:
Site LTAR	.5	.5	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	1	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM	SS-SLIGHTY STICKY S-STICKY VS-VERY STICKY
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	EFI-EXTREMELY FIRM	NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

SG-SINGLE GRAIN M- MASSIVF CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

PR-PRISMATIC Show profile locations and other site features (dimensions, references or benchmark, and North)