Department of Environment, Health and Natura	ì
Division of Environmental Health	
On-Site Wastewater Section	

ources

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Available Space (.1945)

System Type(s) Site LTAR

Location Water Evalua		: Auge	Proper Proper In	Evaluated: 9.23 gn Flow (.1949): Serty Recorded: ndividual	Well Spring	e:	er		
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
112	L-4-68	0-20	SL.	En Gerson	2				
		20-40	SCEIM	nNEstor	? 36-30 3h				14
			a						
									*
					2	4			
Descript	ion		tial Rep	oair System Si	Other Factors (.1946): te Classification (.1948):	P5			

Evaluated By: Others Present:

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		

STRUCTURE
SG-SINGLE GRAIN
M-MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

SC-SANDY CLAY

SIC-SILTY CLAY 0.4 - 0.1

EXPANSIVE

C-CLAY

IV

Show profile locations and other site features (dimensions, references or benchmark, and North)

Show profile locations and other site features (dimensions, references or benchmark, and North)

