

**COUNTY OF HARNETT**  
**Building Inspections Department**  
**Planning Services**

**Certificate of Compliance:** \_\_\_\_\_ **Occupancy:**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Rob Gwente

Address: 872 Cummings Rd

Date: 9/12/17

**Permit Numbers**

Building: \_\_\_\_\_

Electrical: \_\_\_\_\_

Insulation: \_\_\_\_\_

Plumbing: \_\_\_\_\_

Mechanical: \_\_\_\_\_

MFG Home: \_\_\_\_\_

Building Official: [Signature]

39530

ADDRESS : 872 CUMMINGS RD  
CONTRACTOR :  
OWNER : GURULE ROB & MARY JO  
PARCEL : 13-0621- - -0116- - -  
APPL NUMBER: 16-50039530 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : US421NW FOR 6.2MILES/ R@ RAVEN ROCK RD/  
L@ BROWN/ R@ CUMMINGS/ PROPERTY IS ON R  
ABOUT .8 MILES DOWN

STRUCTURE: 000 000 60X80 4BDR CRAWL W/ GARAGE & PATIO



FLOOD ZONE : FLOOD ZONE X  
# BEDROOMS : 4.00 PROPOSED USE : SFD  
SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/05/16	TSG	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002880797
	10/05/16	AP	
A814 01	10/25/16	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002889194
	10/25/16	AP	872 CUMMINGS RD LILLINGTON 27546 T/S: 10/25/2016 03:16 PM SBENNETT -----
B103 01	10/25/16	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002889186
	10/25/16	AP	T/S: 10/24/2016 01:56 PM JBROCK ----- T/S: 10/25/2016 02:04 PM MREARIC -----
P307 01	11/02/16	TSG	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 002892792
	11/02/16	DA	T/S: 11/01/2016 09:21 AM JBROCK ----- CHECK VALVE REQUIRED AT YARD HYDRANT ALSO NO PIPE INSTALLED FROM HYDRANT TO HOUSE
P307 02	11/15/16	TSG	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 002897874
	11/15/16	AP	T/S: 11/14/2016 09:13 AM JFORBES -----
B105 01	11/21/16	TSG	R*OPEN FLOOR TIME: 17:00 VRU #: 002901163
	11/21/16	DA	T/S: 11/18/2016 02:46 PM LBENNETT ----- 1- right side pier missing barrier protection between untreated wood and masonry. left side pier not in contact with double joist and no barrier protection. 2-untreated ledger board in contact with masonry in several locations.
B105 02	11/22/16	TSG	R*OPEN FLOOR TIME: 17:00 VRU #: 002901866
	11/22/16	AP	T/S: 11/21/2016 03:01 PM JFORBES -----
R425 01	2/23/17	TSG	FOUR TRADE ROUGH IN VRU #: 002936342
	2/23/17	DA	1-STRAP COLOUMS OF THREE MEMBERS OR MORE. 2-1.5 10-D NAILS ARE NOT ALLOWED IN HANGERS. 3-PIPE IN ATTIC WILL REQUIRE INSULATION AND A CAP AT FINAL. 4-AIR BARRIER REQUIRED BEHIND MASTER TUB. 5-LABEL DRYER DUCT LENGTH. 6-SEAL TOP OF FURRED OUT WALL LEFT OF TUB/SHOWER ON RIGHT SIDE OF HOUSE. OK TO INSULATE AND SIDE.
I129 01	3/07/17	TSG	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002941078
	3/07/17	AP	T/S: 03/06/2017 08:18 AM JBROCK -----
R425 02	3/07/17	TSG	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002941094
	3/07/17	AP	T/S: 03/06/2017 08:18 AM JBROCK -----
H824 01	6/19/17	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002987212
	6/19/17	AP	T/S: 06/20/2017 10:47 AM KHINSON -----
M305 01	8/08/17	TSG	R*PLUMB SEWER CONNECTION TIME: 17:00 VRU #: 003009065
	8/08/17	AP	T/S: 08/07/2017 08:57 AM LLUCAS ----- T/S: 08/08/2017 01:25 PM SGUY -----

-----  
ADDRESS : 872 CUMMINGS RD SUBDIV: BOBBY B THOMAS & LARRY O THOMA  
CONTRACTOR : PHONE :  
OWNER : GURULE ROB & MARY JO PHONE :  
PARCEL : 13-0621- - -0116- - -  
APPL NUMBER: 16-50039530 CP NEW RESIDENTIAL (SFD)  
-----

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P307 03	8/08/17 8/08/17	TSG AP	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 003009073 T/S: 08/07/2017 08:57 AM LLUCAS ----- T/S: 08/08/2017 01:25 PM SGUY -----
E209 01	8/15/17 8/15/17	TSG DA	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 003011947 T/S: 08/14/2017 08:46 AM BPETRICH ----- SIDE DOOR WILL BE OPEN 1- GARAGE FREEZE RECEP REQUIRED TO BE GFI TYPE.2-COULD NOT LOCATE DISPOSAL CONDUCTOR. *NOTE: THE WINDOWS INSTALLED DO NOT MEET THE U-FACTOR REQUIRED FOR ZONE 4 OF .35 OR LESS. TIS WILL NEED TO BE CORRECTED PRIOR TO BUILDING FINAL
E209 02	8/17/17 8/17/17	TSG AP	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 003013489 T/S: 08/16/2017 10:50 AM JBROCK -----
R429 01	9/12/17	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 003023470 T/S: 09/11/2017 12:14 PM LLUCAS ----- GARAGE DOOR WILL BE UNLOCKED

----- COMMENTS AND NOTES -----