

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Stancil Builders Inc

Address: 350 Oxfordshire Dr
Fuquay-Varina, NC 27526

Date: 8-15-17

Building Official: [Signature]

Permit Numbers

Building: _____
Electrical: _____
Insulation: _____
Plumbing: _____
Mechanical: 1650039858
MFG Home: _____

ADDRESS : 350 OXFORDSHIRE DR
CONTRACTOR : STANCIL BUILDERS INC.
OWNER : STANCIL BUILDERS INC
PARCEL : 08-0652- - -0097- -50-
APPL NUMBER: 16-50039858 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 09/30/2016 09:17 AM LBENNETT --
350 OXFORDSHIRE DR
HWY 401 N TOWARDS FUQUAY- TURN RIGHT ON
BALLARD RD - S/D WILL BE DOWN ON THE
LEFT
T/S: 09/30/2016 11:47 AM LBENNETT --

SUBDIV: HADDEN POINTE III 21LOTS
PHONE : (919) 639-2073
PHONE :

STRUCTURE: 000 000 45X46 3BDR W/GARAGE W/DECK CRAWL

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	1/19/17	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002921807
	1/19/17	AP	T/S: 01/18/2017 12:26 PM DJOHNSON ----- TSP INSPECTION ALSO T/S: 01/19/2017 11:08 AM DETAYLOR ----- T Pole must be stabilized
B103 01	2/28/17	DT	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002938405
	2/28/17	AP	T/S: 02/27/2017 11:25 AM BPETRICH ----- T/S: 02/28/2017 03:45 PM DETAYLOR -----
B104 01	3/08/17	JB	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 002943124
	3/08/17	AP	T/S: 03/08/2017 03:54 PM JBROCK -----
A814 01	3/09/17	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002943116
	3/09/17	AP	350 OXFORDSHIRE DR FUQUAY VARINA 27526 T/S: 03/09/2017 04:00 PM SBENNETT -----
B105 01	3/13/17	BS	R*OPEN FLOOR TIME: 17:00 VRU #: 002944098
	3/13/17	AP	T/S: 03/10/2017 01:23 PM JBROCK ----- T/S: March 13, 2017 09:17 AM BSUTTON -----
R425 01	4/25/17	BS	FOUR TRADE ROUGH IN VRU #: 002962903
	4/25/17	DA	T/S: April 25, 2017 09:45 AM BSUTTON ----- No plans on site
R425 02	4/26/17	BS	FOUR TRADE ROUGH IN VRU #: 002963877
	4/26/17	DA	T/S: April 26, 2017 09:10 AM BSUTTON ----- 1. Cover OSB at rear porch beam. 2. Sleeve drain through foundation. OK to side/insulate
I129 01	5/01/17	BS	R*INSULATION INSPECTION VRU #: 002965599
	5/01/17	AP	T/S: May 01, 2017 08:54 AM BSUTTON -----
R425 03	5/01/17	BS	FOUR TRADE ROUGH IN VRU #: 002965580
	5/01/17	AP	T/S: May 01, 2017 08:54 AM BSUTTON -----
H824 01	7/11/17	AC	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002998102
	XXXXXXXXXX	XXXXXXXXXX	T/S: 07/14/2017 01:43 PM KHINSON -----
H824 02	7/12/17	AC	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002998110
	7/12/17	AP	T/S: 07/14/2017 01:44 PM KHINSON ----- T/S: 07/14/2017 01:44 PM KHINSON -----
R429 01	8/15/17	TI	FOUR TRADE FINAL VRU #: 003012180

8/15/17
8/15/17 AP IVR

COMMENTS AND NOTES -----