

Harnett County

108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

10/31/2019

SUBJECT: **CPSF16-50039942**

BUILDING RESIDENTIAL

To: WELLS DESIGN BUILD, LLC

Here are the results of all Inspections located at 55 SOUTHERN PL:

Inspection Type: ENVIR. HLTH. CONFIRMATION

Scheduled Date/Time: 10/31/2016 Completed Date/Time: 11/10/2016 Inspector: Unassigned Result: APPROVED

Remarks:

Notes: T/S: 10/31/2016 10:08 AM KHINSON ------ T/S: 11/10/2016 10:12 AM KHINSON

Inspection Type: R BLDG FOOTING / TEMP SVC POLE

Scheduled Date/Time: 12/1/2016 Completed Date/Time: 12/1/2016 Inspector: Unassigned Result: APPROVED

Remarks:

Notes: T/S: 11/29/2016 11:48 AM JFORBES ------ would like inspection at 12:00 pm

T/S: 12/01/2016 02:57 PM DETAYLOR ------

Inspection Type: ADDRESS CONFIRMATION

Scheduled Date/Time: 12/9/2016 Completed Date/Time: 12/9/2016 Inspector: Unassigned Result: APPROVED

Remarks:

Notes: 55 SOUTHERN PL LILLINGTON 27546

T/S: 12/09/2016 10:41 AM SBENNETT ------

Inspection Type: R BLDG FOUND & TEMP SVC POLE

Scheduled Date/Time: 12/9/2016 Completed Date/Time: 12/9/2016 Inspector: Unassigned Result: APPROVED

Remarks:

Notes: T/S: 12/08/2016 12:29 PM LBENNETT -----



Harnett County

108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: R OPEN FLOOR Scheduled Date/Time: 12/28/2016 Completed Date/Time: 12/28/2016 Inspector: Unassigned Result: APPROVED

Remarks:

Notes: T/S: 12/22/2016 10:20 AM JBROCK -----

Inspection Type: FOUR TRADE ROUGH IN

Scheduled Date/Time: 2/3/2017
Completed Date/Time: 2/3/2017
Inspector: Unassigned
Result: DISAPPROVED

Remarks:

Notes: T/S: 02/02/2017 09:58 AM DJOHNSON ------

1-front door not installed 2-protect gas line entering fire box. 3-sprinkler system not installed 4-install flashing at front door and seal rear deck fashing at top edge. T/S: 02/21/2017 08:37 AM

KSLATTUM -----

Inspection Type: R INSULATION INSPECTION

Scheduled Date/Time: 2/22/2017 Completed Date/Time: 2/22/2017 Inspector: Unassigned Result: APPROVED

Remarks:

Notes: T/S: 02/21/2017 08:34 AM DJOHNSON ------

T/S: 02/22/2017 03:33 PM DETAYLOR ------ Bonus room floor/garage ceiling are not insulated and no blocking has been installed between trusses. Only an issue if bonus room

is converted to living space in future

Inspection Type: FOUR TRADE ROUGH IN

Scheduled Date/Time: 2/22/2017 Completed Date/Time: 2/22/2017 Inspector: Unassigned Result: APPROVED

Remarks:

Notes: T/S: 02/21/2017 08:34 AM DJOHNSON ------

T/S: 02/22/2017 03:33 PM DETAYLOR ------ Bonus room floor/garage ceiling are not insulated and no blocking has been installed between trusses. Only an issue if bonus room

is converted to living space in future



Harnett County

108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ENVIR OPERATIONS PERMIT

Scheduled Date/Time: 1/23/2019
Completed Date/Time: 1/23/2019
Inspector: Oliver Tolksdorf
Result: APPROVED

Remarks: Notes:

Inspection Type: WATER CONNECTION

Scheduled Date/Time: 4/23/2019 Completed Date/Time: 4/23/2019 Inspector: Ray Holder Result: APPROVED

Remarks: Notes:

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: 4/23/2019 Completed Date/Time: 4/23/2019 Inspector: Ray Holder Result: APPROVED

Remarks: Notes:

Inspection Type: TEMP POWER CERTIFICATION

Scheduled Date/Time: 7/19/2019
Completed Date/Time: 7/19/2019
Inspector: Ray Holder
Result: APPROVED

Remarks: Notes:

Inspection Type: FINAL**
Scheduled Date/Time: 7/29/2019
Completed Date/Time: 7/29/2019
Inspector: Ray Holder
Result: APPROVED

Remarks: Notes: