HTE# 17-5-40629

## Harnett County Department of Public Health

29173

Improvement Permit


A	building permit cannot be issued with only an Improvement Pe	
ISSUED TO: Eunborta O Hones		DANIET Carrel 10
NEW ✓ REPAIR ☐ EXPANSIO	100000	
Type of Structure:	N 🗀 Site improvements require	red prior to Construction Authorization Issuance:
Proposed Wastewater System Type: 25% ne		N. C.
Projected Daily Flow: GPD		
Number of bedrooms: Number of Occup	contr. L may	
Basement Tyes No	ants: <u>6</u> max	
	red based on final location and elevations of facilities	
	Well Distance from well	Permit valid for:
Permit conditions:	Well Distance from Well leet	Permit valid for: Five years  ———————————————————————————————————
		IN EXPIRATION
	1. De Note	
Authorized State Agent::	Ands Date: 2-10-	SEE ATTACHED SITE SKETCH
The issuance of this permit by the Health Department in no way guaran	tees the issuance of other permits. The permit holder is responsible for checking	g with appropriate governing bodies in meeting their requirements. This
site is subject to revocation of the ofte plan, plat, or the intended use c	hanges. The Improvement Permit shall not be affected by a change in ownership	p of the site. This permit is subject to compliance with the provisions of
the Laws and Rules for Sewage Treatment and Disposal and to condition	s of this permit.	
		1 730 - 100 -
	Construction Authorization	
	(Required for Building Permit)	
The construction and installation requirements of Rules .1950, .1952, .19	954, .1955, .1956, .1957, .1958. and .1959 are incorporated by references into	this permit and shall be met. Systems shall be installed in accordance
with the attached system layout.		1
ISSUED TO: Cunherland Homes	TW/ DRODERTY LOCATION ST 77	15 the start of 1 10
1330ED 10	PROPERTY LOCATION OF CE	15 HARNET CENTRUE (B)
	SUBDIVISION DRIMKE	ecte / Masslos LOT # 5
Facility Type:	New Expansion	
Basement?  Yes No Basement Fixt		
Type of Wastewater System** 25%	Rederlina dysten	(Initial) Wastewater Flow: 360 GPD
(See note below, if applicable □)		
25% Re	Sertion (Repair)	
Installation Requirements/Conditions	Number of trenches/	
Septic Tank Size / OOO gallons	Exact length of each trench 240 feet Tr	rench Spacing: Feet on Center
Pump Tank Size 1000 gallons		oil Cover: Sinches
8		(Maximum soil cover shall not exceed
	(Trench bottoms shall be level to +/-1/4"	36" above the trench bottom)
	in all directions)	30 above the trench bottom)
Pump Paguiramente: 6 TDU		/
Pump Requirements:ft. TDH vs	——————————————————————————————————————	inches below pipe
C PC	A	aggregate Depth: inches above pipe
Conditions:		inches total
WATER LINES (INCLUDING IRRIGATION) MUST B	E 10FT. FROM ANY PART OF SEPTIC SYSTEM OR REP.	AIR AREA.
NO UTILITIES ALLOWED IN INITIAL OR REPAIR D		
**!( !' !! / / ./	. ""	
and applicable: I understand the system type specified	is different from the type specified on the application. I a	accept the specifications of this permit.
Owner/Legal Representative Signature:	at, or the intended use changes. The Construction Authorization shall not be tra	Date:
This Construction Authorization is subject to revocation if the site plan, pl	at, or the intended use changes. The Construction Authorization shall not be tra	ansferred when there is a change in ownership of the site. This
Construction Authorization is subject to compliance with the provisions of	the Laws and Rules for Sewage Treatment and Disposal and to the conditions o	of this permit. SEE ATTACHED SITE SKETCH
54	MI PET TOTAS	
Authorized State Agent:	Anhant Date:	2-10-17
	Construction Authorization Expiration Date:	2+0-72

## Harnett County Department of Public Health Site Sketch

PROPERTY LOCATON: DE 2715 Assure TI Carral AD

ISSUED TO: Umberland Homes Free SUBDIVISION Brion Near Merch Merchon LOT # 3

Authorized State Agent: Date: 2-10-17



Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Locat Water Evalu		d: D Aug	Public	te Evaluated: <a>-</a> sign Flow (.1949): 1 perty Recorded:	Well Spring	g 🗆 0	Other		3
P R O F I L	.1940 Landscape Position/	Horizon Depth		ORPHOLOGY .1941	.1942 Soil	OTHER PROFILE FACTO		T	
#	Slope %	(ln.)	Structure/ Texture	Consistence Mineralogy	Wetness/ Color	Soil Depth (IN.)	.1956 Sapro	.1944 Restr	Profile Class
1	400	0-18	1.			Depair (Inc.)	Class	Horiz	& LTAR
		13.40	sce,	GLANONS	32 2.76				-4
							9		
2	C52	0-10	5L 1	Cabinsonp					
		10·40	XL .	antoses o	30: 201				_3
_									
+									
_									
									В

	Repair System	Other Factors (.1946):
system		Site Classification (.1948): P5
	_	Evaluated By:
152	28	Others Present:
-4	. 3	Outers resent.
17.	152	782 26 -4 3