

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ Occupancy: _____

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: BIM Builders LLC

Address: 229 Buffkin Ln
Angier, NC 27501

Date: 12-11-17

Building Official: 

Permit Numbers

Building: _____

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: 1750040765

MFG Home: _____

ADDRESS : 229 BUFFKIN LN SUBDIV:
 CONTRACTOR : BIM BUILDERS LLC PHONE : (919) 894-5741
 OWNER : WILLIAMS JASON R & LORRIE J PHONE :
 PARCEL : 04-0672- - -0004- -05-
 APPL NUMBER: 17-50040765 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 02/17/2017 03:36 PM LBENNETT --
 HEAD TOWARD ANGIER - TURN RIGHT ON
 MATTHEWS MILL POND RD - TURN RIGHT ONTO
 BUFFKIN LN - FOLLOW DIRT RD DRIVE
 THROUGH GATED DRIVE - DRIVEWAY GOES TO
 THE LEFT TO THE HOME SITE
 T/S: 05/24/2017 08:19 AM BPETRICH --
 **** PREMISE 59203919 ****

STRUCTURE: 000 000 59X61 4BDR W/GARAGE W/DECK CRAWL

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
A814 01	5/12/17 5/12/17	SB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002971349 229 BUFFKIN LN ANGIER 27501 T/S: 05/12/2017 09:26 AM SBENNETT -----
B101 01	6/26/17 6/26/17	JLP AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002989145 T/S: 06/26/2017 02:21 PM JPERRY -----
B103 01	7/14/17 7/14/17	JLP AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 002997243 T/S: 07/14/2017 03:29 PM JPERRY ----- T-POLE GOOD
B105 01	7/28/17 7/28/17	JLP AP	R*OPEN FLOOR VRU #: 003004661 T/S: 07/28/2017 01:43 PM JPERRY -----
R425 01	9/22/17 9/22/17	JLP DA	FOUR TRADE ROUGH IN VRU #: 003028565 VOICE MESSAGE LEFT 1-Need engineering on missing LVL in kitchen. 2-Need LVL cutsheet. 3-Missing nails in hurricane clips at corners of the house in bedrooms two and three. 4-Missing hurricane clip in master bedroom. 5-Fire block chases in bedroom one and spare bathroom on both sides of tub.
I129 01	9/29/17 9/29/17	DT AP	R*INSULATION INSPECTION VRU #: 003031481 T/S: 09/29/2017 11:11 AM DETAYLOR -----
R425 02	9/29/17 9/29/17	DT AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003031903 T/S: 09/28/2017 02:41 PM LLUCAS ----- T/S: 09/29/2017 11:11 AM DETAYLOR -----
H824 01	10/17/17 10/17/17	AC AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 003041068 T/S: 10/18/2017 10:35 AM KHINSON ----- T/S: 10/18/2017 10:35 AM KHINSON -----
R429 01	12/11/17 12/11/17	TI APDT	FOUR TRADE FINAL VRU #: 003064383

COMMENTS AND NOTES