

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Name: D & D Constructors Inc.

Address: 189 Heatherwood Dr

Date: 9-7-17

Building Official: James T. Hall

Permit Numbers

Building: _____

Electrical: 17-500403-7

Insulation: _____

Plumbing: _____

Mechanical: _____

MFG Home: _____

ADDRESS : 189 HEATHERWOOD DR SUBDIV: OAKMONT PH 2 SECT 1 30LTS
 CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 OWNER : H & H CONSTRUCTORS INC PHONE :
 PARCEL : 03-9589-01- -1021- -13-
 APPL NUMBER: 17-50040787 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : T/S: 02/22/2017 11:47 AM JBROCK ----
 OAKMONT #181 OFF OF DOCS RD

STRUCTURE: 000 000 42X52.4 4BDR SLAB W/ GARAGE & PORCH
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/27/17	JH	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002964898
	4/27/17	AP	T/S: 04/26/2017 01:52 PM JBROCK ----- T-POLE PASSED -----
A814 01	5/02/17	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002966687
	5/02/17	AP	189 HEATHERWOOD DR LILLINGTON 27546 T/S: 05/02/2017 09:55 AM SBENNETT -----
B103 01	5/02/17	TSG	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002966679
	5/02/17	AP	T/S: 05/01/2017 01:45 PM JBROCK -----
P309 01	5/12/17	JH	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002970531
	5/12/17	AP	T/S: 05/10/2017 04:25 PM JBROCK -----
B111 01	5/16/17	TSG	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002972578
	5/16/17	AP	T/S: 05/15/2017 11:35 AM JBROCK -----
R425 01	6/21/17	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002987170
	6/21/17	DA	T/S: 06/20/2017 10:23 AM JBROCK ----- 1)Missing air barrier under water heater platform.2)Anchor all interior load bearing walls per code.3)Pack out both sides of I joists in half bath that have hangers on them per.4)Balloon frame end wall in living room per plans.5)Repalce allshort nails in roof truss hangers at top of stairs with correct size nails.6)Missing hurricane straps at top of stairs on 2ply trusses going from front to back of house.7)3' head of water on drain line test.8)Light box hanging down from ceiling in hall upstairs. OK TO SIDE DO NOT INSULATE
P307 01	6/26/17	BS	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 002989887
	6/28/17	CA	* OVERRIDE TAKEN BY JBROCK DATE: 06/26/17 TIME: 13:59:07 T/S: 06/26/2017 01:59 PM JBROCK ----- T/S: June 28, 2017 03:50 PM BSUTTON ----- No inspection ticket found and no inspection done
R425 02	6/26/17	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002989044
	6/26/17	DA	T/S: 06/23/2017 10:49 AM JBROCK ----- Item #3 not corrected & missing roof truss hanger at top of stairs middle way of girder truss.
I129 01	7/03/17	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002992196
	7/03/17	CA	T/S: 06/30/2017 08:04 AM JBROCK ----- PER MAT -----
R425 03	7/03/17	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002992204

ADDRESS : 189 HEATHERWOOD DR SUBDIV: OAKMONT PH 2 SECT 1 30LTS
CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
OWNER : H & H CONSTRUCTORS INC PHONE :
PARCEL : 03-9589-01- -1021- -13-
APPL NUMBER: 17-50040787 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	7/03/17	CA	T/S: 06/30/2017 08:04 AM JBROCK PER MAT
B104 01	7/06/17	JB	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 002993657
	7/06/17	AP	T/S: 07/06/2017 10:31 AM JBROCK
I129 02	7/07/17	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002993665
	7/07/17	AP	T/S: 07/06/2017 10:31 AM JBROCK
R425 04	7/07/17	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002993673
	7/07/17	AP	T/S: 07/06/2017 10:31 AM JBROCK
H824 01	7/25/17	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 003004744
	7/25/17	AP	T/S: 07/27/2017 10:41 AM KHINSON
			T/S: 07/27/2017 10:41 AM KHINSON
R125 01	8/01/17	JLP	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 003006038
	8/01/17	AP	T/S: 07/31/2017 01:07 PM JBROCK stone inspection
			T/S: 08/01/2017 02:44 PM JPERRY
E209 01	8/10/17	JLP	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 003010535
	8/10/17	AP	T/S: 08/09/2017 02:01 PM JBROCK
			T/S: 08/10/2017 02:18 PM JPERRY
R429 01	8/30/17	JH	FOUR TRADE FINAL TIME: 17:00 VRU #: 003018934
	8/30/17	DA	T/S: 08/29/2017 01:42 PM JBROCK 1) Light in down stairs bedroom closet closer than 12" from shelf.2)Missing window safety latches per code.3)Need ladder for attic access.
R429 02	9/01/17	JH	FOUR TRADE FINAL TIME: 17:00 VRU #: 003019957
	9/01/17	DP	T/S: 08/31/2017 09:19 AM JBROCK ITEMS #1 WAS NOT CORRECTED & need weatherstrip & insulation for attic access door
R429 03	8/07/17	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 003022092
	9-7-17	AP JH	T/S: 09/06/2017 02:40 PM BPETRICH

COMMENTS AND NOTES